

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Shady Woods	7188 Woods Ln	150	14-205		14-204	Bad tap, right Dropped pipe, severe	73.9 79.2	01/10/2008	Repair tap & pipe	02/04/08	See entry below Project 08-22
	7100 Woods Ln					Ab tap, right, OK Ab tap, left, OK Tap, right, OK RIJ, hvy Ab tap, right, separated Broken joint Tap, left, OK Separated joint	2.3 13.7 38.2 39.1 74.4 80.8 86.8 99.4		Repair joint	1/28/08	See entry above/still did not get a complete run Project 08-15
Shady Woods	7100 Woods Ln	570	14-204		14-205	Offset joint, bad	107.3	01/10/2008	Repair offset	1/31/2008	Project 08-16
Shady Woods	7066 Ridge Drive	100	14-274		14-275	Jet only	100	01/10/2008	Jet only	01/10/08	
Steamboat Run	206 Yorkshire	300	05-22		05-21	Blockage	2' from MH 05-21	01/21/2008	ok	01/21/08	Jet only
Colonial Hills	10677 Williamsburg Dr	405	02-178		02-177	Belly starts Offset joint & tap Tap, left Offset joint Belly stopped Tap, left Belly starts Belly stopped Tap, left, repaired Belly starts Tap, left, OK Belly stopped Belly starts Hole, repaired Repair Tap, left, repaired MH 02-177	20.6 30.2 30.4 31.7 93.9 146.1 146.1 202.0 248.3 283.7 327.0 327.0 369.5 390.0 391.7 399.4 405.0	01/24/2008	Repair tap & joint and/or Slipline		Project 08-163

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Powers Place	10055 Kimberly Ln					Belly starts Belly stops Tap, right, OK Tap, left, OK Tap, 11:00, clay line, bad roots in crack	14.4 38.1 63.1 159.7 180.4		Point Repair	Re-bid 1/21/08	Project 08-27
	10077 Kimberly Ln					Belly starts Belly stops Tap, right, roots/lgt RIJ, lgt Old repair starts Old repair stops RIJ, med Tap, top, OK MH 01-22	222.3 236.8 252.1 252.4 274.4 279.4 284.7 302.4 306.7		Tap repair	Pending	Project 08-164
	10077 Kimberly Ln	307	05-02		01-22	Crack in pipe(past MH)	309.0	01/24/2008	Point repair	Pending	Project 08-165
Forrest Park	944 Treelane	0	14-280		14-281	Tap, left, OK Tap, right, roots/lgt Silt build up	1.8 10.7 52.6	01/28/2008	Emergency Tap Repair Same repair on 1/29/08	01/30/08	Re-done 1/29/08 Project 08-14
Broadview B	7655 Ridgemont	229	15-172		15-174	RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt Repaired tap, R, ok Repaired tap, left Goes to PVC Tap repair, R, ok Pipe repair ends MH 15-174	7.0 31.8 36.7 46.5 52.1 79.8 108.2 135.7 168.7 220.2 228.9	01/28/2008	On Preventative Maint On Slipline Report		
Forrest Park	944 Treelane	158	14-280		13-190	Belly Begins Belly Ends Belly Begins 90° Elbow in pipe turn into MH 13-190	125.8 142.6 156.5 158.3	01/29/2008	Put on Main line replacement (125' to 157') Install New Manhole	09/04/08	Project 08-33
Forrest Park	944 Treelane 950 Treelane (dye test)	161	14-280		14-281	Tap, left, OK Tap, right, roots/lgt Tap, top, coming apart 11 1/4" fitting 11 1/4" fitting MH 14-281	1.0 10.2 62.5 83.5 121.6 161.0	01/29/2008	Repair tap Repair tap	1/30/08 2/11/08	Project 08-14 Project 08-166

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Town	Darby Hills Rd & Jefferson	96	10-63		10-31	Offset joint Offset joint Tap, right, ok Offset joint Offset joint Offset joint Offset joint Offset joint/roots, lgt Offset joint/belly starts Offset joint/belly ends Offset joint Offset joint Offset joint Offset joint Offset joint EOR	6.5 11.6 12.9 18.6 28.9 34.3 38.7 43.8 48.9 53.8 59.3 68.7 73.9 79.1 84.6 89.2 96.2	01/30/2008	Slipline		
Green Springs Valley	8477 Sycamore Dr	0	11-197		11-196	AB tap, right, ok Tap, left, ok Tap, left, ok Offset joint, lgt Offset joint, lgt Grease in pipe 1/2"	35.0 38.6 44.0 64.9 74.6 87.7	01/30/2008	Slipline		Re-entered 2/4/08
Green Springs Valley	8444 Sycamore Dr	216	11-209		11-210	Belly starts Belly ends RIJ, med RIJ, lgt AB tap Tap, repaired, R, ok Tap, repaired, L, ok RIJ, lgt RIJ, lgt Tap, repaired, L, ok AB tap, left EOR	2.7 8.2 18.7 28.9 49.7 85.5 114.6 127.3 137.5 166.7 207.6 216.1	01/30/2008	Slipline		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	4622 Elm Dr					RIJ, lgt, 4 jnts Tap, right, ok crack in 8" by tap	4.1-18.4 31.2 31.2		Slipline Point Repair		Project 08-168
	4600 Elm Dr					AB tap, right RIJ, lgt, 4 jnts Tap, right RIJ, lgt, 2 jnts RIJ, hvy	99.4 145.6-165.7 174.3 176&181.1 186.1		Point Repair		Project 08-169
	4588 Elm Dr					RIJ, lgt, 2 jnts AB tap, right RIJ, lgt, 2 jnts AB tap, right Tap, right, offset&crack	190.3&201.1 207.1 208.1&218.0 304.4 325.2		Repair tap & crack		Project 08-170
	4566 Elm Dr					Tap, left, ok AB tap, right Tap, right, crack in line	357.2 414.5 416.6		Repair tap & crack		Project 08-171
	4555 Elm Dr	422	11-215		11-216	MH, offset pipe	421.6	02/04/2008	Point repair at MH		Project 08-172
Town	510 W Jennings Plum & Jennings					Offset jnt, med tap, top, ok Offset joint Belly Start Offset jnt, med, 2 jnts Protruding tap, top	7.0 7.9 8.8 8.8 13.5&23.4		Slipline Repair Tap		Project 08-142
						Offset jnt, med AB tap, ok Offset jnt, med, 10 jnts Offset jnt Tap, top, ok Offset jnt, med, 7 jnts Tap, top, ok Offset jnt, med, 4 jnts Tap, top, ok Offset jnt, med, 9 jnts Dropped pipe, severe	27.7 29.1 29.8 30.4-81.0 91.4 92.7 93.7-133.7 134.3 135.5-150.6 151.6 152.7-193.1		Repair dropped pipe	03/06/08	Also entered 1/29/08 Project 08-30

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8499 Sycamore 4588 Stonegate Dr (hse in Stonegate/line in back of house)	341	11-197		11-196	AB tap, right, ok tap, left, ok Tap, left, ok Offset joint, lgt Offset joint, lgt Offset joint, lgt Tap, right, root/hvy AB tap, right, ok Tap, left, roots/hvy Offset joint, lgt MH 11-196	34.9 38.5 44.3 50.8 65.4 76.0 88.8 120.6 141.5 337.1 341.4	02/04/2008	Slipline Repair Tap Repair Tap		Project 08-173 Project 08-174 Also entered 1/30/08
Stonegate	8388 Stonegate	213	11-134		11-199	Offset Joint, lgt Offset joint, lgt Offset joint, lgt Offset joint, lgt AB tap, right, ok Tap, left, ok Offset joint, lgt Tap, repaired, R, ok AB tap, right, ok Belly start RIJ, lgt Tap, repaired, R, ok RIJ, lgt RIJ, lgt RIJ, lgt Offset joint, med Offset joint, med Offset joint, med End of Belly	15.4 32.4 38.5 44.7 51.7 59.8 60.8 64.5 97.9 97.9 104.6 144.2 152.0 157.9 173.7 195.8 206.6 212.5	02/04/2008	Slipline		Also entered 1/30/08
Town	419 Section Street	335	09-120		09-122	2 sections Jet only		02/06/2008	ok		Complaint 2/6/08

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8288 Oak	142	11-228		11-210	Tap, right, ok Tap, left, ok AB tap, left Offset joint AB tap, right RIJ, lgt RIJ, lgt Offset joint RIJ, lgt RIJ, med Offset joint RIJ, lgt RIJ, med Tap, right, roots/med RIJ, lgt RIJ, med RIJ, lgt RIJ, med	46.7 49.1 78.1 78.4 80.5 81.4 86.2 91.1 96.1 101.1 106.2 110.7 116.7 121.9 122.8 132.6 137.6 141.7	02/07/2008	Repair Tap		Project 08-222
Green Springs Valley	8099 Chestnut	31	11-232		11-231	RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt RIJ, bad	1.3 6.9 11.4 16.1 21.5 26.7 31.4	02/07/2008	Slipline Redone for CEI Slipline		
Green Springs Valley	8277 Chestnut	88	11-235		11-234	Belly start Tap, repaired, ok	.5 87.7	02/08/2008	Slipline Redone for CEI Slipline		
Green Springs Valley	8088 N Larch	0	11-252		11-255	Belly starts at MH RIJ, med RIJ, med RIJ, med RIJ, lgt RIJ, lgt RIJ, med Rij, lgt AB tap, left, root/lgt RIJ, med RIJ, lgt RIJ, lgt	9.2 11.8 15.7 20.8 26.0 30.9 36.1 37.4 48.4 53.0 63.3	02/08/2008	Slipline Redone for CEI Slipline		Also entered 2/19/08

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8400 Lincoln/ 8433 Chestnut	86	11-237		11-238	Tap, left, OK Offset joint light AB tap, OK Offset joint light Offset joint light Belly start Offset joint light AB tap, left AB tap, right Offset joint Offset joint with tap, R	1.2 3.1 3.6 10.0 14.0 14.0 24.3 81.2 83.6 84.3 86.3	02/11/2008	Repair tap		Project 08-191
Green Springs Valley	8311 Birch Dr	222	11-249		11-259	RIJ, lgt/Belly start RIJ, lgt RIJ, lgt RIJ, med RIJ, lgt RIJ, lgt RIJ, lgt & OJM RIJ, lgt OJM & Belly stops OJM OJM OJM Belly starts OJM & Belly stops EOR	5.0 10.4 15.1 19.7 35.6 40.9 45.7 50.6 126.0 131.1 146.2 150.8 158.9 175.6 221.6	02/19/2008	Slipline		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8277 N Larch Pl	427	11-249		11-261	Belly start	1.0	02/20/2008	Slipline		Project 08-192
						OJM	4.6				
	Roots, lgt	9.5&11.0									
	OJM	29.2&65.5									
	AB tap, left, OK	85.5									
	Belly start	119.6									
	LJ	130.1									
	Tap, left, OK	139.6									
	OJM	147.7									
	AB tap, OK	167.9									
	OJM	180.2									
	LJ	186.4									
	OJM	204.3&216.3									
	OJM	222.6&228.7									
	OJM	241.4									
	Belly stop & pipe crack	271.8									
	OJM	278.2									
	Tap, right, old rep. OK	281.8									
	OJM/cracked pipe, lgt	290.1									
	OJM	296.8&326.8									
	OJM/roots, lgt	338.4									
	OJM	344.2									
	AB tap, OK	346.2									
	RIJ, med	346.9									
	RIJ, med/Belly start	352.6									
	RIJ, bad	358.8									
	RIJ, bad	375.9									
	OJM/roots, med	399.1									
	OJM	424.3									
	EOR	427.4									

<div style="display: flex; justify-content: space-between; font-size: small;"> (Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair </div>													
2008 JET CLEANING													
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments		
Broadview B	8000 Meadow	387	15-211		15-277	Belly Start	19.2	02/20/2008	Slipline				
						OJS	50.8						
						AB tap, right, ok	62.1						
	Ridgemont (need #)					Tap, left, roots	63.8					Repair tap (at 63.8')	Project 08-194
						OJM	79.3						
						LJ	89.6						
						OJM	94.3&99.7						
	8044 Meadow					OJM & LJ	104.9&114.8					Repair tap/8" line offset (at 144.0')	Project 08-195
						OJM	120.0&125.2						
	8044 Meadow					OJM	130.0						
						Tap,R,old rep/8" line offset	144.0					Repair line section & offset jnt (225.6 to 251.8)	Project 08-196
						OJM							
						AB tap, Right, ok	150.7&156.0						
	8088 Meadow					Tap, left, ok	163.0					Repair tap (at 281.3')	Project 08-197
						OJM	165.0						
						OJM	170.1&185.1						
						OJM	190.4&195.8						
						OJM/LJ/roots,igt	200.9&205.5						
						Start of old repair	220.7						
						Tap, right, ok	225.6					Repair tap (at 387.0')	Project 08-198
						End of old repair/offset	323.7						
						jnt/med	251.8						
						RJ, bad	257.0						
						OJM	267.8&272.0						
						AB tap, right	279.2						
						OJM	280.0						
						Tap, left, roos/hvy	281.3						
	OJM	287.1&291.5											
	OJM	297.3&302.4											
	OJM with roots	306.9											
	OJM	312.1											
	Belly starts/bad	313.6											
	OJM	317.5											
	OJM/bad belly stops	322.9											
	OJM/old repair	339.0											
	Tap, R, ok/old repair	340.0											
	OJM/old repair	341.0											
	OJM/roots, igt	358.1											

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8022 N Larch PI	429	11-255		11-252	RIJ, lgt	37.7		Repair dropped pipe (47.9')	Bid 2/25/08	Project 08-199
						Drop pipe, fernco	47.9				
						Tap, right, ok	53.0				
						Tap, left, ok	66.2				
						Offset joint, lgt	82.6				
	Tap, right, ok					138.5	Repair RIJ (possible tap at 414.3')		Bid 2/25/08	Project 08-200	
	Tap, left, ok					141.3					
	RIJ, lgt					151.5					
	AB tap, right, ok					228.0					
	Tap, left, ok					235.0					
	Offset joint, old repair					249.2	Slipline				
	Tap, right, ok					251.5					
	Offset pipe					286.3					
	Tap, right, ok					292.7					
	AB tap, right, ok					302.7					
Tap, left, ok	329.7										
RIJ, lgt	361.9										
RIJ, med	376.5										
AB tap, R, roots/med	387.3										
RIJ, med	393.8										
RIJ, med	408.6	RIJ/possible tap,roots	414.3								
EOR	428.5										
South Broadview	5366 E Timberwood	335	14-54		14-55	Tap, top, maybe hammer	60.8	02/21/2008	Repair tap	Bid 2/26/08	Project 08-201
						Tap, top, ok	70.0				
						Belly starts	112.8				
						OJM	120.7				
						Belly stops	123.8				
	Tap, top, ok					126.2	Slipline				
	Tap, top, ok					161.6					
	Belly starts					207.2					
	Belly stops					230.0					
	OJM					271.8					
	Tap, top, ok					274.5	Repair joint		5/2/08	Project 08-202	
	Belly start					278.5					
	Old repair, ok					281.5					
	OJM					302.2					
	OJM					314.6					
Tap, right, ok	325.4	OJS	334.8								

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Tennyson Terrace	7899 Owens Dr	223	15-51		15-50	RIJ, lgt OJM Start of repair Tap, right, ok End of repair OJM OJM OJM Tap, right, repaired ok AB tap, left, ok OJM AB tap, right ok RIJ, med RIJ, med Tap, top, ok RIJ, lgt & OJM RIJ, severe	28.6 58.7 63.0 66.4 68.5 73.2 83.4 108.5 162.0 170.7 171.2 173.0 178.3 188.4 206.7 213.5 223.2	02/21/2008	Slipline Re-TV to check if repair needed		
Heritage Place	6599 Heritage	243	21-51		21-50	Tap, right, ok Tap, top, ok Tap, right, ok Tap, right, roots, hv RIJ RIJ, med	68.1 120.6 145.5 222.5 251.1 243.0	02/25/2008	Slipline Repair Tap	2/29/08	Project 08-203
Springvale	6666 Springvale	51	21-59		20-167	Belly start Silt in pipe	23.1 51.3	02/25/2008	Need to jet & re-tv		
Springvale	6666 Springvale	15	21-59		21-60	MH 21-60	15	02/25/2008	OK	02/25/08	
Twin Oaks	7355 Oaklawn	38	15-124		15-123	MH 15-123	38.2	02/26/2008	OK	02/26/08	
Twin Oaks	7355 Oakdale Dr	175	15-117		15-124	OJM/LJ RIJ, lght, grease RIJ, med	1.1 133.4 143.8	02/26/2008	Partial/Jet flush		
Twin Oaks	7355 Oaklawn	300	15-124		15-122	OJM Tap, right, Protruding	5.0 6.6	02/26/2008	Repair Tap	02/27/08	Project 08-204 See below and 2/28/08
Twin Oaks	7411 Oaklawn	0	15-122		15-124	Tap, protruding	2	02/26/2008	Repair Tap		Project 08-206 See above and 2/28/08

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Tennyson Terrace	7922 Lincoln Ave in back of house	313	15-59		15-58	Tap, left, ok LJ, light Belly start RIJ, lgt w/LJ, lgt OJM Tap, right, ok RIJ, med LJ, lgt Tap, left, ok Tap, roots, lgt Tap, right, ok Tap, right, ok AB tap, left Tap, right, ok Tap, protruding, left MH 15-58	17.3 25.0 28.0 104.4 109.6 111.0 122.0 161.3 193.0 228.4 255.4 302.8 304.7 306.9 313.0	02/27/2008	Slipline Repair tap		Project 08-207
Twin Oaks	7344 Oakdale 7377 Oaklawn 7366 Oakdale 7377 Oaklawn	137	15-124		15-122	Tap, right, OK Tap, left, roots Hammer tap, right Hammer tap, L top, rts Roots jnt, hvy (problem)	7.5 52.2 94.5 117.2 136.7	02/28/2008	Repair tap Repair tap Repair tap Repair problem (WB &/or RP need to look at DVD)	Pending Pending Pending Bid 2/26/08	Project 08-210 Project 08-211 Project 08-212 Project 08-208 Also entered 2 time 2/26/08
Tennyson Terrace	Pine Drive	200	15-39		15-220	Jet only	320	03/03/2008	Jet only	03/03/08	
Tennyson Terrace	4266 Pine Dr.	200	15-40		15-39	Jet only	200	03/03/2008	Jet only	03/03/08	
Broadview	7633 Meadow	80	15-177		15-176	Tap, left, OK Tap, right, OK Offset joint, severe	67.2 79.6 80.3	03/04/2008	Point repair	03/14/08	Project 08-213
Tennyson Terrace	7766 Owens Dr Betw 7800/7822 Owens	425	15-37		15-36	Point repair, OK Tap, left, roots, lgt Tap, left, OK Tap, left, OK Tap, left, OK Tap, left, OK Tap, left, roots, lgt Tap, right, OK Tap, left, OK Tap, left, OK MH 15-36	20.1 35.7 63.7 120.5 234.7 310.4 344.7 349.3 412.9 425.1	03/04/2008	Repair Tap Repair Tap		Project 08-214 Project 08-215

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
	6577 Heritage Dr					Tap, right, ok Tap, top, ok Tap, right, offset Tap, right, ok/old repair RIJ, Lgt, LJ at top RIJ, lgt RIJ, med RIJ, lgt RIJ, med RIJ, lgt	69.2 122.1 146.2 222.8 253.9 268.4 274.5 278.7 283.6 288.8		Repair tap		Project 08-217
Heritage Place	6610 Heritage Dr	294	21-54		21-55	Offset old repair/severe	293.9	03/05/2008	Point repair		Project 08-218
Green Springs Valley	4366 W Larch Inv as 4399 W Larch	12	11-266		11-267	RIJ, med RIJ, lgt RIJ, lgt Elbow to left	2.5 7.3 12.3 12.3	03/10/2008	Install MH	03/20/07	See entry below Project 08-85
Green Springs Valley	8155 N Larch	224	11-267		11-266	Damaged area	224	03/10/2008	Repair damaged area after MH installed above		See entry above Project 08-221
Kingston Eastbrook	3233 Brookfield Dr	284	16-99		16-103	Tap, left, ok RIJ, lgt RIJ, lgt Tap, left, ok Belly start Belly stops MH 16-103	81.0 173.4 183.6 222.4 268.5 283.8 283.8	03/10/2008	Slipline		
Ridgewood	6522 Hemlock Way	0	20-49		20-50			03/10/2008	Need to jet & re-tv On Slipline		
Springvale	6600 Valley Rd	135	20-150		20-149	Belly start Belly stops AB tap, left, ok AB tap, right ok Belly start Tap, top, ok Tap, top, ok RIJ, lgt AB tap, right ok RIJ, lgt RIJ, lgt	0.0 37.6 90.2 97.4 102.1 111.8 114.2 123.3 124.5 132.5 135.3	03/10/2008	On Slipline		
Village Lane	Village Lane	272	10-112		10-110	Jet only	272	03/11/2008	Jet only	03/11/08	
Green Springs Valley	8333 Chestnut Dr	4	11-236		11-235	Belly start	3.5	03/11/2008	Too much water to see On Slipline		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplin	(Lime) tap and main repair													
2008 JET CLEANING																			
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments								
Springvale	6588 Center Ridge	254	20-162		20-163	LJ, med	4.2	03/14/2008	On Slipline	Bid 2/22/08	Also see TV 10/12/07 & 10/15/07								
						AB tap, right, clay	46.1												
	RIJ, lgt					47.4	Repair Tap												
	RIJ, med, LJ/lgt					62.2													
	RIJ, lgt					72.2	Repair Tap												
	RIJ, lgt					91.2													
	Tap, left, roots, hvly					97.8	Repair Tap												
	AB tap, left, clay					100.0													
	6599 Valley Rd					110.4	RIJ, lgt		110.4			03/14/2008	20-163	RIJ, lgt	125.4	03/14/2008	Repair Tap	Bid 2/22/08	Project 08-91
							Tap, left, OK (rep PVC)		143.5										
RIJ, lgt		150.1																	
Tap, right, roots/hvly, clay		156.4	Repair Tap																
RIJ, lgt		191.9																	
RIJ, lgt		202.2	Repair Tap																
LJ, lgt	216.8																		
6611 Valley Rd	224.1	Tap, right, roots/hvly	224.1	03/14/2008	20-163	AB tap, OK, clay	253.4	03/14/2008	Repair Tap	Pending	Project 08-92								
		AB tap, OK, clay	253.4																
6600 Center Ridge	254.4	PT, left, roots/hvly(2-3")	254.4	03/14/2008				03/14/2008	Repair Tap	Bid 2/22/08	Project 08-93								
Heritage Place III	6700 Valley Rd	28	20-172		20-171	LJ, lgt	16.2	03/17/2008	Repair tap		Project 08-223								
						LJ, lgt	21.7												
						PT, left at 11:00/PVC	27.6												

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplin	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Broadview B	4600 Broadview Dr (complaint 7677 Broadview)	393	15-187		15-188	AB Tap, L, clay ok Tap, R, pvc ok Tap, left, pvc ok Offset jnt, clay-truss, med Tap, R, ok Offset jnt, truss-clay, rep'd AB tap, L, ok AB tap, R, ok Tap, L, pvc, ok 3" crk betw clay & new rep Tap, R, pvc, ok AB tap, L, clay ok AB tap, R, clay ok Tap, left, ok Cly-tru/rep'd/offset 1 1/2" Tap, R, truss offs ins tap PVC RIJ, lgt RIJ, lgt MH 15-188	56.1 58.5 63.8 158.4 161.8 168.1 225.1 226.7 255.8 277.1 279.3 324.6 326.6 349.1 361.8 365.3 372.6 382.5 393.2	03/17/2008	3" crack at 277.1' is at a Stemaly repair (Wayne will discuss with Leon) Re-TV done 5/22/08 - shows OK	05/22/08	Also see 5/22/08
Heritage Place III	Need address (Jamestown)	112	20-147		20-172	Tap, top, ok, clay Hammer tap, top, right Belly start Belly end	25.5 93.5 93.5 112.3	03/17/2008	Repair Tap		Project 08-224
Busler's/Pine Dr	Need address (Pine Dr) Need address (Pine Dr)	162	15-223		15-225	Tap, right, ok RIJ, lgt RIJ, lgt, leak sm drops RIJ, med, leak steady stream Hammer tap, R, PVC (no leak, prot, or offsets) Hammer tap, R, PVC (no leak, prot, or offsets) Jnt, sm sep, steady stream from top AB tap, right, ok EOR	26.5 32.9 77.4 87.7 89.9 91.7 117.6 124.9 162.3	03/18/2008	Repair Tap Repair Tap Put on Slipline		Project 08-225 Project 08-226
Busler's/Pine Dr	Walgreens	266	15-223		15-224	EOR	266.2	03/18/2008	ok	03/18/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) slipline	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Newburgh Plaza South	8077 Rose Hill Dr	245	10-148		10-151	LJ Belly start Belly ends AB tap, right, ok, clay AB tap, left, ok, clay Belly start PT, 1" top, ok Belly ends Tap, top, ok PVC AB tap, left, ok, caly AB tap, right, ok, clay PT, 11-00, PVC, 2-3"	9.6 68.1 84.2 91.9 94.1 147.9 151.3 158.9 174.8 191.9 193.4 245.0	03/24/2008	NSD to Repair tap		
Town/Fosters	724 Cypress	328	10-108		10-107	OJM Belly start Old repair/Truss start end of repair/offset jnt RIJ, lgt AB tap, L,leak,roots/lgt Belly ends Belly starts New repair/starts,truss Tap, top,ok, new rep. Old repair, truss Tap, L, offset 1"&leaking End of old repair AB tap, ok MH 10-107	26.5 35.0 36.1 43.7 77.9 128.4 159.2 170.0 179.6 181.4 223.6 226.8 232.9 306.6 327.9	03/24/2008	Slipline		
Lexington Development	Corner of Sable Ridge & Essex Dr	317	26-49		26-50	Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss MH 26-50	15.3 32.8 127.1 222.9 311.6 317.4	03/31/2008	ok	03/31/08	
Lexington Development	Corner of Sable Ridge & Essex Dr	0	26-49		26-44	Tap, left, ok, truss Tap, right, ok truss Tap, left, ok, truss MH 26-44	139.4 140.8 226.8 238.2	03/31/2008	ok	03/31/08	See TV done 5/14/08
River Ridge	Wynstone Ct.	60	19-77		19-79	Jet only	60	04/01/2008	Jet only	04/01/08	
River Ridge	Wynstone Ct.	200	19-77		19-78	Jet only	200	04/01/2008	Jet only	04/01/08	
River Ridge	Wind Point Dr.	150	19-75		19-77	Jet only	150	04/01/2008	Jet only	04/01/08	
River Ridge	Wind Point Dr.	260	19-75		19-76	Jet only	260	04/01/2008	Jet only	04/01/08	
River Ridge	Waterstone Ct.	250	19-67		19-75	Jet only	260	04/01/2008	Jet only	04/01/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
High Pointe Centre N.	Vacant Lot	380	12-122		12-121	Jet only	380	04/01/2008	Jet only	04/01/08	
High Pointe Centre N.	Vacant Lot	376	12-123		12-122	Jet only	376	04/01/2008	Jet only	04/01/08	
High Pointe Centre N.	Vacant Lot	380	12-129		12-130	Jet only	380	04/01/2008	Jet only	04/01/08	
High Pointe Centre N.	8777 Vann Rd.	300	12-134		12-135	Jet only	300	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	8855 Vann Rd.	420	12-133		12-134	Jet only	420	04/02/2008	Jet only	04/02/08	
Newburgh Plaza South	8077 Rose Hill Dr	350	10-149		10-149	Jet only	350	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	High Pointe Way	300	12-124		12-125	Jet only	300	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	Bell Road	175	12-126		12-125	Jet only	175	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	Bell Road	30	12-126		12-77	Jet only	30	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	Vann Road	348	12-135		12-136	Jet only	348	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	High Pointe Way	400	12-128		12-129	Jet only	400	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	High Pointe Way	200	12-127		12-128	Jet only	200	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	High Pointe Way	60	12-124		12-127	Jet only	60	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	High Pointe Way	200	12-124		12-123	Jet only	200	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	Vann Road	400	12-132		12-133	Jet only	400	04/02/2008	Jet only	04/02/08	
High Pointe Centre N.	Vann Road	400	12-131		12-132	Jet only	400	04/03/2008	Jet only	04/03/08	
County	Master L.S.	70	08-23		12-131	Jet only	70	04/03/2008	Jet only	04/03/08	
County	Master L.S.	400	08-22		08-23	Jet only	400	04/03/2008	Jet only	04/03/08	
County	Master L.S.	400	08-21		08-22	Jet only	400	04/03/2008	Jet only	04/03/08	
Lakeridge	2366 Lakeridge Dr.	180	23-69		23-53	Jet only	180	04/03/2008	Jet only	04/03/08	
County	Master L.S.	400	08-20		08-21	Jet only	400	04/03/2008	Jet only	04/03/08	
County	Master L.S.	400	08-19		08-20	Jet only	400	04/03/2008	Jet only	04/03/08	
County	Master L.S.	300	08-18		08-19	Jet only	400	04/03/2008	Jet only	04/03/08	
County	Master L.S.	70	08-18		08-17	Jet only	70	04/03/2008	Jet only	04/03/08	
Lexington Development	walgreens	80	26-57		26-56	Pipe separated 6-8" MH 26-56	73.8 79.8	04/02/2008	Repair main		
Blue Lake	2988 Briarcliff	133	22-01		22-02	Tap, R, ok Tap, L, ok Tap, Top, ok Tap, L, ok Tap, L, ok	1.6 5.3 37.5 127.3 132.6	04/08/2008	Incomplete		
Town	406 Monroe St	508	09-49		09-56	2 sections Jet only/rags & grit		04/08/2008	ok	04/08/08	Complaint 4/8/08
Kenosha Hills	4877 Eau Claire	558	03-04A		03-06	Jet only		04/23/2008	ok	04/23/08	Complaint 4/23/08
Bell Oaks Place	Lakeshore Drive United Fidelity Bank	240	11-168		11-167	Jet only Hole in Main Mud & silt	15	05/05/2008	Repair hole in main	05/05/08	Project 08-239 Complaint 5/5/08
Bell Oaks Place	Lakeshore Drive	220	11-168		11-169	Jet only Silt & grease		05/05/2008	ok	05/05/08	Complaint 5/5/08
Bell Oaks Place	Lakeshore Drive	370	11-162		11-168	Jet only Silt & grease		05/05/2008	ok	05/05/08	Complaint 5/5/08

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Lexington Development	Sable Ridge	198	26-57		26-58	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-58	16.6 92.9 119.1 191.8 198.0	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	97	26-57		26-59	MH 26-59	96.7	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	159	26-59		26-60	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 26-60	13.2 85.4 151.1 159.1	05/12/2008	ok	05/12/08	
Lexington Development	Corner of Sable Ridge & Thornbury Circle	112	26-59		26-61	Tap, R, PVC ok MH 26-61	90.8 111.6	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	87	26-61		26-65	Tap, R, PVC ok MH 26-65	55.6 86.7	05/12/2008	ok	05/12/08	
Warrick Place	Apple Center	22	16-113		?	EOR	22.1	05/13/2008	ok	05/13/08	
Lexington Development	Sable Ridge	280	26-61		26-62	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-62	81.7 106.5 168.8 271.6 280.1	05/13/2008	ok	05/13/08	
Lexington Development	Oak Park Dr	93	26-62		26-63	Tap, R, PVC ok MH 26-63	78.8 92.9	05/13/2008	ok	05/13/08	
Lexington Development	Oak Park Dr	73	26-63		26-64	Tap, R, PVC ok MH 26-64	65.0 73.0	05/13/2008	ok	05/13/08	
Lexington Development	Ashley Dr & Sable Ridge	170	26-56		26-52	Tap, R, PVC ok Tap, R, PVC ok MH 26-52	43.2 142.0 170.0	05/13/2008	ok	05/13/08	
Lexington Development	Corner Ashford & Ashley	239	26-53		26-52	Tap, top, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-52	143.5 145.5 225.3 238.7	05/13/2008	ok	05/13/08	
Lexington Development		55	26-53		26-55	Tap, L, PVC ok MH 26-55	48.6 55.0	05/14/2008	ok	05/14/08	
Lexington Development	Ashford Dr	47	26-53		26-54	Tap, R, PVC ok Tap, R, PVC ok MH 26-54	4.4 38.6 46.5	05/14/2008	ok	05/14/08	
Lexington Development		133	26-42		26-43	Tap, L, PVC ok Tap, L, PVC ok MH 26-43	46.6 126.5 133.0	05/14/2008	ok	05/14/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Lexington Development		254	26-42		26-44	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-44	91.1 147.8 179.1 253.7	05/14/2008	ok	05/14/08	
Lexington Development		143	26-42		26-41	Tap, R, PVC ok Tap, R, PVC ok MH 26-41	38.6 127.6 143.1	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	58	26-51		26-44	MH 26-45	58.4	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	282	26-51		26-52	Tap, L, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 26-52	18.2 19.9 129.1 133.9 282.3	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	239	26-44		26-49	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-49	8.1 93.9 94.8 238.9	05/14/2008	ok	05/14/08	Also see TV done 3/31/08
Lexington Development	Essex Dr	101	26-44		26-45	MH 26-45	100.7	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	41	26-46		26-45	MH 26-45	40.7	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	176	26-46		26-47	Tap, R, PVC ok MH 26-47	30.5 175.6	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	170	26-47		26-48	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-48	15.2 115.0 114.2 120.1	05/14/2008	ok	05/14/08	
Lexington Development	Glenview Dr	110	26-41		26-40	MH 26-40	109.7	05/14/2008	ok	05/14/08	
Lexington Development		160	26-39		26-40	MH 26-40	159.9	05/15/2008	ok	05/15/08	
Lexington Development		91	26-39		26-38	MH 26-38	91.0	05/15/2008	ok	05/15/08	
Lexington Development		272	26-28		26-38	Tap, L, PVC ok MH 26-38	175.8 272.1	05/15/2008	ok	05/15/08	
Lexington Development		124	26-28		26-27	MH 26-27	124.2	05/15/2008	ok	05/15/08	
Lexington Development		191	26-28		26-29	Tap, R, PVC ok Tap, R, PVC ok MH 26-29	35.8 130.1 191.2	05/15/2008	ok	05/15/08	
Lexington Development		222	26-31		26-29	Tap, L, PVC ok Tap, L, PVC ok MH 26-29	58.0 159.5 221.9	05/15/2008	ok	05/15/08	
Lexington Development		225	26-31		26-33	Tap, top, PVC ok Tap, R, PVC ok MH 26-33	61.8 162.2 224.5	05/15/2008	ok	05/15/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Lexington Development		215	26-33		26-34	Tap, R, PVC ok Tap, L, PVC ok MH 26-34	106.8 179.0 214.7	05/15/2008	ok	05/15/08	
Lexington Development		203	26-33		26-35	Tap, R, PVC ok Tap, R, PVC ok MH 26-35	57.8 153.5 202.6	05/15/2008	ok	05/15/08	
Lexington Development		213	26-35		26-36	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 26-36	100.1 105.2 200.0 213.1	05/15/2008	ok	05/15/08	
Lexington Development		200	26-35		26-37	Belly End belly Tap, R, PVC ok Tap, R, PVC ok MH 26-37	6.0 17.0 143.8 194.0 200.3	05/15/2008	ok	05/15/08	
Huntington Ridge	4378 Huntington Ridge Ct	104	07-161		07-162	Tap, L, PVC ok Tap, R, PVC ok MH 7-162	69.4 75.9 104.2	05/16/2008	ok	05/16/08	
Huntington Ridge	4378 Huntington Ridge Ct	238	07-161		07-59	MH 7-59	237.5	05/16/2008	ok	05/16/08	
Huntington Ridge	4338 Huntington Ridge Ct	239	07-163		07-162	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-162	9.6 57.1 122.8 238.7	05/16/2008	ok	05/16/08	
Huntington Ridge	4338 Huntington Ridge Ct	234	07-163		07-164	Tap, R, PVC ok Tap, R, PVC ok MH 07-164	73.8 163.2 233.6	05/16/2008	ok	05/16/08	
Huntington Ridge	4308 Huntington Ridge	40	07-164		07-165	Jet	40.0	04/07/2008	ok	04/07/08	Silt
Huntington Ridge	Empty Lot	251	07-165		07-166	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 7-166	57.7 135.1 218.1 244.4 250.8	05/16/2008	ok	05/16/08	
Huntington Ridge	4378 Huntington Ridge Ct	0	07-162		07-161	Tap, L, PVC ok Tap, R, PVC ok MH 7-161	24.2 31.4 104.9	05/19/2008	ok	05/19/08	Also see 5/16/08
Huntington Ridge	4378 Huntington Ridge Ct	9	07-162		07-168	MH 7-168	9.0	05/19/2008	ok	05/19/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Huntington Ridge	4378 Huntington Ridge Ct	333	07-168		07-167	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 7-167	99.6 151.8 189.8 254.5 261.2 324.7 326.0 332.9	05/19/2008	ok	05/19/08	
Huntington Ridge	4378 Huntington Ridge Ct	292	07-168		07-169	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-169	99.1 177.2 254.7 291.5	05/19/2008	ok	05/19/08	
Huntington Ridge	4228 Huntington Ridge Ct	296	07-170		07-171	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 7-171	31.9 56.1 110.8 124.6 189.2 202.9 290.0 295.6	05/19/2008	ok	05/19/08	
Huntington Ridge	4228 Huntington Ridge Ct	221	07-170		07-169	Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-169	48.4 63.8 138.5 220.9	05/19/2008	ok	05/19/08	
Huntington Ridge		292	07-172		7-169	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 7-169	18.7 96.6 174.3 251.9 291.5	05/19/2008	ok	05/19/08	
Huntington Ridge	9311 Emily Ct	381	07-173		07-174	Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 07-174	22.8 36.4 101.5 115.6 182.6 194.2 272.6 285.7 370.4 374.4 381.4	05/20/2008	ok	05/20/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Huntington Ridge	9311 Emily Ct	137	07-173		07-172	Tap, L, PVC ok Tap, R, PVC ok MH 07-172	42.0 46.5 136.8	05/20/2008	ok	05/20/08	
Huntington Ridge	9299 Millicent Ct	378	07-176		07-177	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-177	20.9 98.9 163.7 255.2 332.6 360.1 377.7	05/20/2008	ok	05/20/08	
Huntington Ridge	9299 Millicent Ct	69	07-176		07-175	MH 07-175	69.0	05/20/2008	ok	05/20/08	
Huntington Ridge		179	07-175		07-172	Tap, R, PVC ok Tap, R, PVC ok MH 07-172	43.0 120.6 179.4	05/20/2008	ok	05/20/08	
Huntington Ridge		73	07-175		07-178	Tap, L, PVC ok Tap, L, PVC ok MH 07-178	23.2 68.1 73.4	05/20/2008	ok	05/20/08	
Fieldcrest Place		53	07-131		07-130	Tap, R, PVC ok Tap, R, PVC ok MH 07-130	7.1 48.5 52.7	05/20/2008	ok	05/20/08	
Fieldcrest Place		139	07-131		07-126	Tap, L, PVC ok MH 07-126	75.6 138.6	05/20/2008	ok	05/20/08	
Fieldcrest Place		312	07-125		07-124	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-124	34.0 120.4 194.5 277.0 311.5	05/20/2008	ok	05/20/08	
Fieldcrest Place		263	07-125		07-126	Tap, L, PVC ok Tap, L, PVC ok MH 07-126	15.2 253.8 262.6	05/20/2008	ok	05/20/08	
Fieldcrest Place		282	07-125		07-132	MH 07-132	281.6	05/20/2008	ok	05/20/08	
Fieldcrest Place	Empty Lot	162	07-123		07-122	Tap, L, ok Tap, L, ok Tap, L, ok MH 07-122	32.0 114.5 156.0 162.3	05/21/2008	ok	05/21/08	
Fieldcrest Place	Empty Lot	387	07-123		07-124	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 07-124	36.4 113.6 191.7 273.3 351.8 386.9	05/21/2008	ok	05/21/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fieldcrest Place	Empty Lot	208	07-127		07-126	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 07-126	28.0 31.2 100.2 103.2 173.0 174.7 208.0	05/21/2008	ok	05/21/08	
Fieldcrest Place	Empty Lot	359	07-127		07-128	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 07-126	31.2 33.2 108.5 111.4 243.2 248.2 322.2 324.3 359.0	05/21/2008	ok	05/21/08	
Fieldcrest Place	4550 Fieldcrest Place	218	07-128		07-129	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 07-129	28.8 32.4 100.7 104.4 175.2 178.8 211.2 217.7	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	73	07-159		07-158	Tap, L, ok Tap, L, ok MH 07-158	62.6 65.7 72.6	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	44	07-159		07-160	Tap, R, ok MH 07-160	38.9 44.0	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	82	07-158		07-156	MH 07-156	82.0	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	110	07-156		07-157	Tap, R, ok Tap, R, ok MH 07-157	9.8 103.4 110.4	05/21/2008	ok	05/21/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Broadview B	4600 Pine Dr	0	15-187		15-188	AB Tap, L, ok Tap, R, ok Tap, left, ok Pipe repair ok Pipe repair ok 1/4" Offset, clay-truss Tap, R, ok Tap, L, ok 1/4" Offset, truss-clay AB tap, L, ok AB tap, R, ok Tap, L, ok 1/4" offset, clay-truss Tap, R, ok 1/8" offset, clay-truss AB tap, L, ok AB tap, R, ok 1/4" offset Tap, L, ok clay-truss 1/8" offset, all truss 1/4" offset, clay-truss 1/8" offset, truss-clay MH 15-188	54.0 56.4 61.4 135.5 152.5 154.9 158.3 165.3 165.5 221.8 223.8 252.2 272.2 275.5 276.6 321.2 323.2 345.3 346.1 350.1 357.9 362.8 391.8	05/22/2008	ok	05/22/08	Also see 3/17/08
Blackberry Hill		83	07-155		07-156	Tap, R ok MH 07-156	5.9 83.0	05/22/2008	ok	05/22/08	
Blackberry Hill		214	07-155		07-154	Tap, R, ok MH 07-154	180.9 213.8	05/22/2008	ok	05/22/08	
Fall Creek	Pemrose Dr (empty lot)	309	03-150		03-149	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok 1/4" offset, truss-truss Tap, R, ok MH 03-149	24.7 87.3 146.2 209.6 269.6 275.6 304.1 309.0	05/22/2008	ok	05/22/08	
Fall Creek	Pemrose Dr (empty lot)	362	03-151		03-150	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-150	24.0 85.3 148.9 209.8 269.2 333.6 362.0	05/23/2008	ok	05/23/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	Pemrose Dr (empty lot)	249	03-151		03-152	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-152	35.1 97.8 157.7 217.1 249.0	05/23/2008	ok	05/23/08	
Fall Creek	Pemrose Dr (empty lot)	77	03-153		03-152	Tap, R, ok Tap, R, ok MH 03-152	9.4 67.0 76.5	05/23/2008	ok	05/23/08	
Fall Creek	Pemrose Dr (empty lot)	114	03-153		03-154	Tap, L, ok Tap, L, ok MH 03-154	31.7 90.9 113.9	05/23/2008	ok	05/23/08	
Fall Creek	4763 Pemrose Dr	368	03-154		03-156	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-156	80.4 85.5 148.0 153.1 209.5 215.1 272.2 277.9 336.5 341.0 367.9	05/23/2008	ok	05/23/08	
Fall Creek	4757 Pemrose Dr	119	03-159		03-154	Tap, R, ok Tap, R, ok MH 03-154	22.0 84.0 119.0	05/23/2008	ok	05/23/08	
Fall Creek	4757 Pemrose Dr	34	03-159		03-155	MH 03-155	33.9	05/23/2008	ok	05/23/08	
Fall Creek	Empty Lot	308	03-157		03-156	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Belly start 1" MH 03-156	25.6 30.0 86.1 91.7 146.4 151.9 209.5 213.6 275.6 280.2 305.0 307.6	05/27/2008	ok	05/27/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	253	03-157		03-158	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-158	22.2 26.9 83.6 88.0 144.5 149.2 210.5 215.6 245.4 248.5 252.6	05/27/2008	ok	05/27/08	
Fall Creek	Empty Lot	372	03-148		03-146	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-147	34.6 94.6 156.3 215.7 280.0 341.0 371.9	05/27/2008	ok	05/27/08	
Royal Highlands	5511 Lakeside Dr	0	Royal Sta		20-97	Roots & grease	44.6 ??	05/27/2008	Repair tap Repair joint	Done Done	Project 08-243 Project 08-246
Royal Highlands	5533 Lakeside Dr	0	Royal Sta		20-97	RIJ, Hvy	60.1	05/28/2008	Point repair	Done with Proj. 08-243 & 246	Project 08-245
Royal Highlands	5533 Lakeside Dr 5533 Lakeside Dr	149	20-97		Royal Sta	Tap, R, roots hvy RIJ, hvy	72.1 88.4	05/28/2008	Repair tap Point Repair	Done with Proj. 08-243 & 246	Project 08-244 Project 08-245
Fall Creek	10658 Fall Creek	392	03-125		03-126	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Crack in pipe Tap, R, ok Tap, L, ok MH 03-126	96.3 100.4 159.3 163.9 225.8 229.3 290.0 294.7 308.0 355.8 361.1 392.1	05/29/2008	Point repair	7/31/08	Project 08-247

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	10730 Fall Creek	286	03-125		03-122	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 03-122	66.4 71.4 227.6 231.2 285.8	05/29/2008	ok	05/29/08	
Fall Creek	10730 Fall Creek	284	03-125		03-128	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-128	52.0 55.7 218.9 223.2 277.1 283.6	05/29/2008	ok	05/29/08	
Fall Creek	Empty Lot	386	03-144		03-116	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-116	12.6 16.9 77.6 81.7 136.9 141.9 194.4 199.5 259.9 264.5 317. 322.5 386.4	06/03/2008	ok	06/03/08	
Fall Creek	Empty Lot	388	03-144		03-145	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-145	34.7 158.2 155.3 209.9 217.9 269.8 274.6 331.5 338.1 388.0	06/03/2008	ok	06/03/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	10542 Titan Dr	386	03-120		03-121	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-121	.8 1.2 33.0 38.5 93.1 98.1 160.0 165.2 222.6 227.4 287.9 292.8 352.8 358.2 386.4	06/04/2008	ok	06/04/08	
Fall Creek	Empty Lot	113	03-146		03-147	Tap, R, ok Tap, R, ok MH 03-147	82.0 108.4 113.1	06/04/2008	ok	06/04/08	
Fall Creek	Empty Lot	308	03-145		03-146	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Mud in pipe MH 03-146	23.5 26.6 82.2 84.9 143.2 146.1 210.2 212.4 298.3 308.3	06/04/2008	ok	06/04/08	
Fall Creek	10630 Titan Dr	382	03-121		03-122	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-122	24.5 29.5 89.7 94.4 156.2 159.0 218.5 226.9 283.9 288.1 382.2	06/05/2008	ok	06/05/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	10542 Fall Creek Dr	392	03-127		03-126	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-126	7.4 35.3 39.1 98.8 103.6 164.5 169.6 229.8 234.7 293.7 298.2 358.1 363.3 392.3	06/05/2008	ok	06/05/08	
Fall Creek	4808 Marble Dr	173	03-118		03-92	Tap, R, ok Tap, R, ok Tap, R, ok MH 03-92	26.6 85.0 145.6 172.9	06/05/2008	ok	06/05/08	
Fall Creek	4808 Marble Dr	367	03-118		03-119	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-119	19.3 28.3 142.9 202.1 265.5 324.4 360.9 366.8	06/05/2008	ok	06/05/08	
Fall Creek	4892 Marble Dr	109	03-131		03-130	Tap, R, ok Tap, L, ok MH 03-130	84.0 89.3 109.4	06/05/2008	ok	06/05/08	
Fall Creek	Marble Dr	324	03-131		03-132	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-132	1.4 38.7 111.6 160.1 215.2 282.1 315.8 323.8	06/05/2008	ok	06/05/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	378	03-129		03-128	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Left side wall is 1/4" Tap, L, ok MH 03-128	24.7 29.9 88.4 93.6 151.8 156.7 217.5 224.4 280.6 285.1 342.1 348.4 377.9	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	389	03-129		03-130	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, pipe leaking Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-130	24.5 29.1 89.6 94.5 151.5 151.5 156.1 215.7 220.0 282.1 287.1 344.1 348.3 389.3	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	35	03-137		03-136	Tap, R, ok Tap, R, ok MH 03-136	1.0 25.0 35.3	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	151	03-136		03-135	Offset Jnt, 1/2" Tap, R, mud Tap, L ok Tap, L, ok MH 03-135	48.4 100.9 105.7 146.7 151.0	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	81	03-136		03-138	Tap, R, ok Belly start Belly end MH 03-138	24.6 75.6 80.9 80.9	06/06/2008	ok	06/06/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	10627 Tecumseh	302	03-141		03-138	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-138	25.9 84.6 147.9 208.8 272.3 302.0	06/06/2008	ok	06/06/08	
Fall Creek	10627 Tecumseh	312	03-141		03-142	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-142	24.5 84.4 146.7 207.6 268.7 306.9 311.6	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	403	03-134		03-133	Belly start 1 1/2" Belly stop Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Pipe 1/2 full of mud MH 03-137	0.0 18.5 20.5 25.5 86.0 90.2 148.9 153.9 214.5 220.4 279.5 283.4 343.4 349.2 383.2 386.1 397.0 402.6	06/09/2008	ok	06/09/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	381	03-134		03-135	Belly start 1 1/2" Belly stop Tap, R, ok Tap, L, ok Tap, R, ok 1/3 mud Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok 1/2 mud Tap, R, ok MH 03-135	0.0 15.2 27.0 31.8 93.1 96.0 154.4 160.2 220.7 226.2 283.0 288.4 356.0 381.1	06/09/2008	ok	06/09/08	
ITT	10999 ITT Technical Inst.	22	04-11		ITT LS	ITT L.S.	21.6	06/09/2008	ok	06/09/08	
ITT	10999 ITT Technical Inst.	146	04-11		04-10	Belly start 1 1/2" Offset Jnt, 1/4" Belly stop MH 04-10	21.5 43.1 77.0 145.5	06/09/2008	ok	06/09/08	
County	Stahl Road	384	04-09		04-08	MH 04-08	384.2	06/09/2008	ok	06/09/08	
County	Stahl Road	0	04-09		04-10	Belly start Water over camera 1/2" pipe	10.2 34.9	06/09/2008	Jet & Re-TV done 6/16/08	06/09/08	Also see 6/16/08
County	Stahl Road	372	04-07		04-08	MH 04-08	371.9	06/09/2008	ok	06/09/08	
Springston	8111 Covington Ct	265	12-24		12-79	Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok MH 12-79	2.5 13.8 39.9 102.9 143.0 213.4 264.5	06/12/2008	ok	06/12/08	
Fall Creek	4751 Pemrose Dr	72	03-155		03-116	Belly start 1/3 of pipe Tap, L, ok Belly stops MH 03-116	68.0 71.9 135.0 135.0	06/12/2008	Main Line Repair List		Partial TV done on 5/23/08 Project #08-248

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Twin Oaks	7433 Oaklawn Dr	325	15-121		15-122	RIJ, med RIJ, lgt Cracked pipe, roots/lgt Tap, R, ok Tap, L, ok Tap, top, ok RIJ, lgt Cracked pipe, roots/lgt RIJ, lgt Sign of new repair Tap, L, ok End new repair RIJ, hvy RIJ, hvy New repair Tap, R End of new repair Tap, L, roots, hvy offset joint, small MH 15-122	46.3 52.8 89.5 90.6 95.3 103.3 167.8 177.2 180.1 190.6 191.3 196.0 218.0 223.0 246.7 250.0 258.0 272.0 303.2 325.2	06/16/2008	On Slipline List Root cut TV was also done 11/14/07 & 4 repairs were put on repair list (Wayne will review DVD)		Project 08-157 Project 08-158 Project 08-159 Project 08-160 (Repairs from the 11/14/07 Tv done)
Venetian Way	Stahl Road	42	04-09		04-10	MH 04-10	42.0	06/16/2008	ok	06/16/08	Also see 6/9/08
Venetian Way	Stahl Road	347	04-06		04-07	Tap, L, ok Tap, L, ok MH 04-07	.2 340.2 346.8	06/16/2008	ok	06/16/08	
Venetian Way	Stahl Road	307	04-06		04-05	MH 04-05	306.6	06/16/2008	ok	06/16/08	
Venetian Way	Lateral @ Oncology Hematology (3699 Epworth)	328	04-04		04-05	Tap, L, ok Joint in flow Tap, R, ok MH 04-05	159.0 184.7 198.3 327.8	06/16/2008	Contractor to investigate	10/13/08	Project 08-260
Venetian Way		274	04-03		04-04	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok MH 04-04	42.7 92.0 96.4 139.4 239.7 274.0	06/17/2008	ok	06/17/08	
Venetian Way		289	04-03		04-02	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 04-02	42.5 48.0 138.9 186.7 190.0 238.6 289.2	06/17/2008	ok	06/17/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Venetian Way		271	04-02		04-01	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 04-01	42.1 46.1 142.5 251.5 265.7 270.6	06/17/2008	ok	06/17/08	
Arbor Pointe		285	08-29		08-28	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 08-28	97.0 117.0 259.5 274.8 284.6	06/17/2008	ok	06/17/08	
Arbor Pointe		390	08-30		08-29	Tap, R, PVC ok Trap, L, pvc, ok Crack in pipe, RC Tap, R, pvc, ok Tap, L, pvc, ok Tap, R, pvc, ok MH 08-29	66.4 71.0 84.4 215.2 262.4 352.5 389.9	06/17/2008	Leon to review what should be done		
Arbor Pointe		208	08-30		08-31	MH 08-31	207.6	06/17/2008	ok	06/17/08	
Arbor Pointe		106	08-35		08-33	Tap, R, pvc ok Tap, R, pvc ok MH 08-33	94.3 98.8 105.7	06/17/2008	ok	06/17/08	
Arbor Pointe		139	08-35		08-34	Tap, R, pvc ok Tap, R, pvc ok MH 08-34	62.9 131.8 138.7	06/17/2008	ok	06/17/08	
Arbor Pointe		108	08-36		08-37	Tap, R, ok Tap, R, ok MH 08-37	37.1 103.5 108.4	06/18/2008	ok	06/18/08	
Arbor Pointe		258	08-39		08-40	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 08-40	40.7 97.1 100.2 143.1 257.6	06/18/2008	ok	06/18/08	
Arbor Pointe		288	08-39		08-38	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 08-38	34.1 39.0 141.0 185.6 189.2 238.6 287.9	06/18/2008	ok	06/18/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Arbor Pointe		306	08-38		08-37	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, L, ok MH 08-37	39.7 44.0 143.7 189.8 194.2 246.8 303.8 305.6	06/18/2008	ok	06/18/08	
Arbor Pointe		354	08-36		08-35	Tap, L, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 08-35	41.5 144.7 231.7 325.3 354.2	06/18/2008	ok	06/18/08	
Town	507 E Main Complaint	184	09-125		09-126	Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Tap, R, ok Aband tap, R, ok Aband tap, L, ok Tap, L, ok Stopped approx 15' from MH	7.5 14.7 20.1 24.7 49.3 54.0 84.0 98.9 106.0 118.0 130.2 184.0	06/19/2008	ok	06/19/08	
Arbor Pointe		287	8-31		8-32	Tap, R, ok MH 08-32	98.4 286.6	06/19/2008	ok	06/19/08	
Arbor Pointe		136	8-31		8-25	Tap, L, ok MH 08-25	107.6 136.0	06/19/2008	ok	06/19/08	
Arbor Pointe		289	8-25		8-25A?	Tap, R, ok MH 08-25A	114.0 289.2	06/19/2008	ok	06/19/08	
Arbor Pointe		17	8-25		8-24	MH 08-24	16.8	06/19/2008	ok	06/19/08	
Arbor Pointe		88	8-25		8-26	Tap, L, ok MH 08-26	81.6 87.6	06/19/2008	ok	06/19/08	
Bellmoore		378	12-147		12-148	Tap, R, ok MH 12-148	334.5 378.1	06/20/2008	ok	06/20/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Bellmoore		393	12-147		12-145	Tap, L, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 12-145	71.0 130.7 133.8 331.4 334.5 387.2 393.1	06/20/2008	ok	06/20/08	
Bellmoore		242	12-143		12-144	Tap, L, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, L, ok MH 12-144	5.6 116.7 119.5 229.6 232.6 242.0	06/20/2008	ok	06/20/08	
Bellmoore		383	12-143		12-142	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 12-142	38.0 76.6 79.0 128.3 227.2 276.8 279.7 336.3 382.7	06/20/2008	ok	06/20/08	
Bellmoore		370	12-141		12-142	Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 12-142	33.8 237.0 274.1 279.0 359.0 370.0	06/20/2008	ok	06/20/08	
Bellmoore		82	12-149		12-148	MH 12-148	81.5	06/20/2008	ok	06/20/08	
Bellmoore		130	12-149		12-150	MH 12-150	130.0	06/20/2008	ok	06/20/08	
Bellmoore		145	12-145		12-146	Tap, L, ok MH 12-146	137.8 144.9	06/20/2008	ok	06/20/08	
Bellmoore		112	12-145		12-144	Tap, L, ok MH 12-144	88.3 111.6	06/20/2008	ok	06/20/08	
Bellmoore		159	12-141		12-140	MH 12-140	158.7	06/20/2008	ok	06/20/08	
Bellmoore		395	12-140		12-139	MH 12-138	395.0	06/23/2008	ok	06/23/08	
Bellmoore		97	12-139		12-138	Tap, R, ok MH 12-138	94.1 96.7	06/23/2008	ok	06/23/08	
Bellmoore		78	12-141		12-151	Tap, L, ok MH 12-141A	72.9 78.4	06/23/2008	ok	06/23/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Mansfield	4671 Marble Ct	222	03-114		03-115	Tap, L, ok Tap, L, ok MH 03-115	69.3 128.6 221.7	06/23/2008	ok	06/23/08	
Mansfield	4671 Marble Ct	353	03-114		03-113	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-118	32.5 102.8 172.1 243.9 318.9 352.8	06/23/2008	ok	06/23/08	
Mansfield	4611 Marble Ct	321	03-113		03-112	Tap, R, ok Tap, R, ok Tap, R, ok MH 03-112	29.1 102.7 189.4 320.5	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	96	03-111		03-112	MH 03-112	96.1	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	142	03-111		03-110	Belly start 1 1/2" Tap, R, ok Tap, top, ok Belly end MH 03-110	0.0 54.1 55.7 142.0 142.0	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	51	03-111		03-52	MH 03-52	51.1	06/23/2008	ok	06/23/08	
Mansfield	4522 Marble Ct	0	03-109		03-110	Too much flow		06/24/2008	Re-TV		
Mansfield	4595 Mansfield Dr	128	03-108		03-109	Tap, L, ok Tap, R, ok MH 03-109	69.6 71.2 127.9	06/24/2008	ok	06/24/08	
Mansfield	4595 Mansfield Dr	358	03-108		03-107	Belly start Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Belly stop MH 03-107	0.0 86.9 91.0 158.7 162.6 231.2 234.8 301.5 310.0 358.0 358.0	06/24/2008	ok	6/24/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Mansfield	4595 Mansfield Dr	296	03-108		03-104	Tap, R, ok Tap, L, ok Belly start Tap, L, ok Tap, R, ok Belly stop MH 03-104	41.7 46.3 61.0 224.5 228.6 295.8 295.8	06/24/2008	ok	06/24/08	
Mansfield	4725 Mansfield Dr	275	03-105		03-106	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-106	29.8 102.2 169.6 244.5 274.8	06/26/2008	ok	06/26/08	
Mansfield	4695 Mansfield Dr	351	03-106		03-107	Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-107	21.3 95.9 166.4 170.5 238.4 245.6 309.9 314.0 351.2	06/26/2008	ok	06/26/08	
Mansfield	4725 Miranda	223	03-101		03-102	Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-102	2.7 6.6 42.1 44.0 113.8 115.9 182.6 186.5 223.1	06/27/2008	ok	06/27/08	
Mansfield	4715 Marble Dr	350	03-104		03-103	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-103	96.3 101.3 169.2 173.0 239.6 244.2 311.0 316.2 350.2	06/27/2008	ok	06/27/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Mansfield	4695 Miranda Dr	85	03-102		03-103	Tap, R, ok Tap, L, ok Belly start Too much water	35.1 39.0 85.0	06/27/2008	Re-TV after jet	06/27/08	
Mansfield	4645 Miranda Dr	175	03-103		03-102	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Too much water	26.5 30.0 97.0 102.0 169.4 175.2	06/27/2008	Re-TV after jet	06/27/08	
Ivy Glen	Ivy Glen Drive	320	03-63		03-64	Jet only	320.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	Ivy Glen Drive	60	03-63		C.O.	Jet only	60.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10811 English Ct. - back	400	03-60		03-59	Jet only	400.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10900 Thorndale Dr.	30	03-59		C.O.	Jet only	30.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10799 English Ct.	30	03-61		03-60	Jet only	30.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10788 English Ct.	400	03-57		03-58	Jet only	400.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10788 English Ct.	200	03-56		03-57	Jet only	200.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10788 English Ct.	210	03-56		03-60	Jet only	210.0	06/30/2008	Jet only	06/30/08	
Ivy Glen	10800 Thorndale Dr.	200	03-60A		03-60	Jet only	200.0	06/30/2008	Jet only	06/30/08	
Lincolnwood	4333 Cherry Blossom	240	31A-14		31A-15	Jet only	240.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Cherry Blossom	240	31A-12		31A-14	Jet only	240.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Cherry Blossom	400	31A-10		31A-09	Jet only	400.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Cherry Blossom	100	31A-09		31A-08	Jet only	100.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Cherry Blossom	210	31A-12		31A-11	Jet only	210.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Cherry Blossom	200	31A-11		31A-10	Jet only	200.0	07/07/2008	Jet only	07/07/08	
Lincolnwood	Sherri Lee Ln.	260	31A-17		31A-16	Jet only	260.0	07/08/2008	Jet only	07/08/08	
Lincolnwood	Kimwood	190	31A-02		31A-01	Jet only	190.0	07/08/2008	Jet only	07/08/08	
Lincolnwood	Kimwood	300	31A-03		31A-02	Jet only	300.0	07/08/2008	Jet only	07/08/08	
Lincolnwood	Kimwood	400	31A-04		31A-03	Jet only	400.0	07/08/2008	Jet only	07/08/08	
Lincolnwood	Kimwood	380	31A-06		31A-05	Jet only	380.0	07/08/2008	Jet only	07/08/08	
Waterstone Village	5716 Waterstone Village	160	30-66		30-91	Belly start Belly end MH 30-91	0.0 160.0 160.0	07/11/2008	ok	07/11/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Waterstone Village	Empty Lot	425	30-92		30-91	Tap, top, ok Tap, top, ok Tap, top, ok offset jnt, 1/2" Tap, L, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-91	2.6 34.5 73.1 93.6 101.8 150.8 166.6 221.2 232.3 285.2 296.8 361.9 377.2 425.4	07/11/2008	ok	07/11/08	
Waterstone Village	Empty Lot	0	30-67		30-68	Tap, top, ok Tap, top, ok Tap, top, ok	19.7 60.7 116.8	07/14/2008	Incomplete/too much fog to see	Re-TV done 7/21/08	Also see 7/21/08
Lakevale Estates	7422 Eastview Ct.	47	13-92		13-94	Tap, R, AD Roots	22.4 47.0	07/14/2008	Point repair/tap	07/15/08	Project 08-252
Lakevale Estates	7422 Eastview Ct.	115	13-94		13-92	Roots	114.7	07/14/2008	Point repair/tap	Same rep. as above	Project 08-252
Waterstone Village	5844 Waterstone Village	359	30-69		30-68	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-68	46.0 97.7 165.0 220.7 280.6 345.2 358.6	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	292	30-90		30-85	MH 30-85	292.2	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	292	30-90		30-91	MH 30-91	292.0	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	347	30-89		30-90	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Mud, too deep MH 30-90	18.3 31.3 83.0 97.8 137.2 151.8 202.2 216.3 292.8 307.1 338.7 347.0	07/15/2008	ok	07/15/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Waterstone Village	Empty Lot	309	30-89		30-88	Tap, top, ok Tap, top, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-88	16.8 30.5 69.7 84.5 125.8 149.3 149.3 188.5 204.0 266.2 306.2 309.4	07/15/2008	ok	07/15/08	
Waterstone Village	5844 Waterstone Village	307	30-69		30-70	Tap, top, ok Tap, top, ok Offset jnt, 1/4" Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-70	3.4 42.6 43.3 67.7 130.7 194.6 258.0 305.6 307.2	07/15/2008	ok	07/15/08	
Waterstone Village	2906 Zachery Ct.	345	30-86		30-87	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-87	29.9 43.6 95.6 109.5 160.6 174.9 214.0 228.8 279.4 293.2 323.9 331.7 344.7	07/16/2008	ok	07/16/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Waterstone Village	2906 Zachery Ct.	385	30-86		30-85	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-85	4.2 18.9 57.5 71.7 123.2 136.9 188.3 202.2 254.4 268.2 332.4 347.9 384.5	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	372	30-72		30-71	Begin Small Belly 1/3 Belly ends Tap, top, ok Tap, top, ok Begin Small Belly Belly Ends Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-71	8.0 40.0 82.5 147.4 185.0 205.0 210.0 262.7 327.3 365.0 372.3	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	133	30-72		30-73	Tap, top, ok Tap, top, ok MH 30-73	75.4 90.1 132.9	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	24	30-72		30-74	MH 30-74	24.2	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	217	30-74		30-75	Tap, top, ok Tap, top, ok Tap, top, ok MH 30-75	42.7 101.5 164.7 216.9	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	118	30-74		30-81	Tap, top, ok Tap, top, ok MH 30-81	76.4 90.9 118.3	07/17/2008	ok	07/17/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Waterstone Village	2905 Zachery Ct.	393	30-83		30-84	Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok MH 30-84	7.2 21.0 60.2 73.7 125.1 141.0 190.2 203.9 255.9 268.8 334.0 347.9 393.0	07/17/2008	ok	07/17/08	
Waterstone Village	Empty Lot	371	30-76		30-77	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-77	1.0 37.2 99.5 152.6 217.7 280.7 342.3 371.2	07/17/2008	ok	07/17/08	
Waterstone Village	Empty Lot	338	30-83		30-82	Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok MH 30-82	30.2 46.2 96.5 110.4 150.8 169.0 214.0 229.5 280.7 294.7 321.5 327.1 337.5	07/17/2008	ok	07/17/08	
Waterstone Village	Empty Lot	340	30-78		30-77	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-77	62.2 118.2 182.1 251.2 301.8 340.2	07/18/2008	ok	07/18/08	
Waterstone Village	Empty Lot	181	30-78		30-79	MH 30-79	181.0	07/18/2008	ok	07/18/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Waterstone Village	Empty Lot	343	30-79		30-80	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-80	31.2 46.1 111.0 124.2 190.6 206.5 249.5 263.8 313.2 327.5 343.2	07/18/2008	ok	07/18/08	
Waterstone Village	Empty Lot	292	30-84		30-79	MH 30-79	291.6	07/21/2008	ok	07/21/08	
Waterstone Village	Empty Lot	292	30-84		30-85	MH 30-85	292.0	07/21/2008	ok	07/21/08	
Waterstone Village	2833 Megan Dr.	351	30-81		30-80	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-80	14.4 26.5 76.2 88.5 141.5 155.9 195.1 209.8 260.0 274.4 325.6 339.7 351.1	07/21/2008	ok	07/21/08	
Waterstone Village	5796 Waterstone Dr	349	30-68		30-67	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-67	48.2 94.9 160.0 224.9 289.0 330.1 348.7	07/21/2008	ok	07/21/08	Also see 7/14/08
Kenosha Hills	4877 Kenosha Hills (Compl. 4877 Eau Clair)	11	03-07		03-06	Entire line full of grease	10.6	09/03/2008	Investigate grade issue		
Town	111 Sharon Rd. Complaint 8400 Sharon Rd	0	10-106		10-161 (dupl. CEI to chg to 10-159)	Too much water & grease	0.0	09/03/2008	Jet & Re-Tv done 9/4/08		See 9/4/08 Project 08-268

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Town	111 Sharon Rd. Complaint 8400 Sharon Rd	166	10-106		10-161 (dupl. CEI to chg to 10-159)	Belly start Grease on R. side (1' +) PT, top 1/2", tap ok PT, top 1/2", tap ok Belly end MH 10-161	0.0 46.0 108.0 125.0 166.0 166.0	09/04/2008	Line replacement CEI project		Project 08-268
Town	617 E. Main	0	09-137		09-155	Joint sep. New repair Tap, R, ok	48.0 180.0 250.0	09/19/2008	ok	09/19/08	Also see below
Town	625 E. Main	396	09-155		09-137	New repair Aban tap Tap, top, ok Tap, top, ok New Repair Tap, top, ok Tap, top, ok EOR	27.0 45.3 99.5 126.3 211.3 241.6 304.5 396.4	09/19/2008	ok Done for complaint	09/19/08	
Lincoln Point	Pecka Ditch Line	90	New MH 21-98 Inv Siphon		New MH 21-99 Inv Siphon		90	09/24/2008	ok	09/24/08	Jet only/no TV
Windsor Pointe	112 Southgate Blvd.	250	06-14		06-10	Jet only	250	09/25/2008	Jet only	09/25/08	
Windsor Pointe	205 Auburn St.	95	06-08A		06-08	Jet only	95	09/25/2008	Jet only	09/25/08	
Windsor Pointe	200 Fairfax	276	06-10		06-06	Jet only	276	09/26/2008	Jet only	09/26/08	
Windsor Pointe	200 Fairfax	199	06-10		06-11	Jet only	199	09/26/2008	Jet only	09/26/08	
Windsor Pointe	116 Westbriar	280	06-06		06-05	Jet only	280	09/26/2008	Jet only	09/26/08	
Windsor Pointe	116 Westbriar	198	06-06		06-07	Jet only	198	09/26/2008	Jet only	09/26/08	
Windsor Pointe	300 Westbriar	60	06-05		06-04	Jet only	60	09/26/2008	Jet only	09/26/08	
Windsor Pointe	124 Alexandria	380	06-30		06-18	Jet only	380	09/26/2008	Jet only	09/26/08	
Windsor Pointe	124 Alexandria	30	06-30		06-30A	Jet only	30	09/26/2008	Jet only	09/26/08	
Windsor Pointe	101 Temple Dr.	387	06-34		06-30	Jet only	387	09/26/2008	Jet only	09/26/08	
Windsor Pointe	117 Temple Dr.	310	06-76		06-34	Jet only	310	09/26/2008	Jet only	09/26/08	
Windsor Pointe	117 Temple Dr.	70	06-76		06-34A	Jet only	70	09/26/2008	Jet only	09/26/08	
Windsor Pointe	125 Temple Dr.	70	06-34A		06-29	Jet only	70	09/26/2008	Jet only	09/26/08	
Windsor Pointe	125 Temple Dr.	170	06-34A		06-17	Jet only	170	09/26/2008	Jet only	09/26/08	
Windsor Pointe	125 Temple Dr.	60	06-29		06-28	Jet only	60	09/26/2008	Jet only	09/26/08	
Windsor Pointe	121 Reston Dr.	400	06-17		06-14	Jet only	400	09/26/2008	Jet only	09/26/08	
Green Springs Valley	8211 Oak Dr.	360	11-212		11-213	Jet only	360	09/29/2008	Jet only	09/29/08	
Summit Pointe	6200 Summit Pointe Way	300	20-196		20-209	Draining slow	300	10/21/2008	ok	10/21/08	Jet only/no TV

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Forest Park	702 Forest Park (compl.)	0	14-257		13-241	Belly start Belly end Tap, L, roots, bad Rap, L, roots, bad Tap, L, roots, minor Tap, right MH 13-241 RIJ, med RIJ, lgt	114.0 140.5 161.7 286.5 307.6 314.0 351.7	12/01/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Forest Park	714 Carole Place	0	14-257		13-241	Belly start Belly end Protruding tap, right Cant get by	0.0 12.0 52.0	12/04/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Forest Park	634 Forest Park Dr	0	13-241		14-257	Tap, R Tap, L Tap, L Tap, R Tap, L Tap, R Tap, L Tap, R PT, L Can't get by	.2 19.0 149.9 151.6 171.0 173.2 194.5 196.2 258.0	12/04/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Roslin Industrial Park	Victoria National	350	33-12		33-13	Jet only	350.0	12/04/2008	ok	12/04/08	
Roslin Industrial Park	Victoria National	350	33-11		33-12	Jet only	350.0	12/04/2008	ok	12/04/08	
Roslin Industrial Park	Victoria National	400	33-10		33-11	Jet only	400.0	12/05/2008	ok	12/05/08	
Roslin Industrial Park	Victoria National	325	33-09		33-10	Jet only	325.0	12/08/2008	ok	12/08/08	
Roslin Industrial Park	Victoria National	400	33-08		33-09	Jet only	400.0	12/08/2008	ok	12/08/08	
Roslin Industrial Park	Victoria National	420	33-07		33-08	Jet only	420.0	12/08/2008	ok	12/08/08	
Roslin Industrial Park	Victoria National	375	33-06		33-07	Jet only	375.0	12/08/2008	ok	12/08/08	
Roslin Industrial Park	Victoria National	300	32-04		32-05	Jet only	300.0	12/09/2008	ok	12/09/08	
Roslin Industrial Park	Victoria National	350	32-05		32-06	Jet only	350.0	12/09/2008	ok	12/09/08	
Roslin Industrial Park	Victoria National	300	33-07		33-03	Jet only	300.0	12/09/2008	ok	12/09/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 JET CLEANING											
SUBDIVISION	ADDRESS	DISTANCE CLEANED	MH#	TO	MH#	Type	Footage Location	Date of Cleaning	Recommended Resolution	Date Resolved	Comments
Alanton	8053 Cedar Point Dr. Comp. 8025 Cedar Point	192	12A-09		12A-10	Tap, R, ok Tap, L, ok Tap R, ok Tap, L, ok Small belly start Belly end Tap, R, ok Tap, L, MH 12A-10	23.9 28.5 93.0 95.8 126.8 130.2 154.5 156.8 192.2	12/09/2008	ok	12/09/08	
Green Springs Valley	8333 Poplar Dr (Compl. 8297 Oak Dr.)	0	11-210		11-211	Tap, R, ok Tap, R, roots, hvy Roots, hvy PT, L	98.9 151.9 168.0	12/09/2008	Re-TV see 12/12/08		
Green Springs Valley	8297 Oak Dr. (Compl. Same address)	0	11-211		11-210	Offset jnt, new rep., tap L	5.0 28.0	12/10/2008	Re-TV see 12/12/08		
Green Springs Valley	8400 Sycamore 8297 Oak Dr. 8388 Sycamore 8366 Sycamore Complaint 8297 Oak Dr	276	11-210		11-211	Tap, R, O/S main, OK Tap, R, ok Tap, R, root, hvy Tap, L, mud&roots, hvy AB tap, L AB tap, R OJM, 1/2" (new rep.) Tap, R, ok Tap, R, hammer, roots MH 11-211	147.2 163.8 165.7 200.1 231.7 243.1 245.0 271.9 275.6	12/12/2008	Tap repair Tap repair Point repair Tap repair		Project 08-272 Project 08-272 Project 08-273 Project 08-274
Field Stone B	4211 Stone Garden (Compl. 4255 Stone Garden)	0	11-103		11-32	Tap, L, ok Tap, T, ok Tap, L, ok Roots hvy, grease	10.2 18.0 106.8 120.0	12/12/2008	Jet & see Re-TV done 12/16/08 for repairs		Project 08-275
Fieldstone	Next to 4244 Wind Hill Ln & Empty Lot (Compl. 4255 Stonegarden Rd)	0	11-32		11-103	Tap, L, ok Tap, R, ok Belly start	73.3 117.1 180.2	12/15/2008	Jet & see Re-TV done 12/16/08 for repairs		Project 08-275

