

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Shady Woods	7188 Woods Ln 2nd tap to 7199 Woods	79	14-205		14-204	Bad tap, right Dropped pipe,severe	73.9 79.2	01/10/2008	Repair tap & pipe	02/04/08	See entry below Project 08-22
	7100 Woods Ln					Ab tap, right, OK Ab tap, left, OK Tap, right, OK RIJ, hvy Ab tap, right, separated Broken joint Tap, left, OK Separated joint	2.3 13.7 38.2 39.1 74.4 80.8 86.8 99.4		Repair joint	1/28/08	See entry above/still did not get a complete run Project 08-15
Shady Woods	7100 Woods Ln	107	14-204		14-205	Offset joint, bad	107.3	01/10/2008	Repair offset	1/31/2008	Project 08-16
Colonial Hills	10677 Williamsburg Dr	405	02-178		02-177	Belly starts Offset joint & tap Tap, left Offset joint Belly stopped Tap, left Belly starts Belly stopped Tap, left, repaired Belly starts Tap, left, OK Belly stopped Belly starts Hole, repaired Repair Tap, left, repaired MH 02-177	20.6 30.2 30.4 31.7 93.9 146.1 146.1 202.0 248.3 283.7 327.0 327.0 369.5 390.0 391.7 399.4 405.0	01/24/2008	Repair tap & joint and/or Slipline		Project 08-163

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Powers Place	10055 Kimberly Ln	307	05-02		01-22	Belly starts	14.4	01/24/2008	Slipline	Re-bid 1/21/08	Project 08-27
	10077 Kimberly Ln					Belly stops	38.1		Point Repair		
						Tap, right, OK	63.1		Point Repair		
					Tap, left, OK	159.7					
						Tap, 11:00, clay line, bad roots in crack	180.4				
						Belly starts	222.3			Pending	Project 08-164
					Belly stops	236.8		Tap repair			
					Tap, right, roots/lgt RIJ, lgt	252.1		Tap repair			
						Old repair starts	252.4				
						Old repair stops	274.4				
						RIJ, med	279.4				
						Tap, top, OK	284.7				
						MH 01-22	302.4				
						Crack in pipe(past MH)	306.7		Point repair	Pending	Project 08-165
							309.0	01/24/2008			
Forrest Park	944 Treelane	0	14-280		14-281	Tap, left, OK	1.8	01/28/2008	Emergency Tap Repair	01/30/08	Re-done 1/29/08
						Tap, right, roots/lgt	10.7		Same repair on 1/29/08		Project 08-14
						Silt build up	52.6				
Broadview B	7655 Ridgemont	229	15-172		15-174	RIJ, lgt	7.0	01/28/2008	On Preventative Maint		
						RIJ, lgt	31.8				
						RIJ, lgt	36.7				
						RIJ, lgt	46.5				
						RIJ, lgt	52.1				
						Repaired tap, R, ok	52.1				
						Repaired tap, left	79.8				
						Goes to PVC	108.2				
						Tap repair, R, ok	135.7				
						Pipe repair ends	168.7				
						MH 15-174	220.2		On Slipline Report		
							228.9				
Forrest Park	944 Treelane	158	14-280		13-190	Belly Begins	125.8	01/29/2008	Put on Main line replacement (125' to 157')		Project 08-33
						Belly Ends	142.6				
						Belly Begins	156.5				
						90° Elbow in pipe turn into MH 13-190	158.3				
									Install New Manhole	09/04/08	
Forrest Park	944 Treelane 950 Treelane (dye test)	161	14-280		14-281	Tap, left, OK	1.0	01/29/2008	Repair tap Repair tap		Project 08-14 Project 08-166
						Tap, right, roots/lgt	10.2				
						Tap, top, coming apart	62.5				
						11 1/4" fitting	83.5				
						11 1/4" fitting	121.6				
						MH 14-281	161.0				

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Town	510 W Jennings	0	09-12		09-11	Offset Joint, med	6.8	01/29/2008	Repair Tap	Bid 2/13/08	Project 08-142
	Tap, top, OK					7.7					
Stonegate	8366 Stonegate Dr	0	11-134		11-199	Offset joint	8.7	01/30/2008	Slipline	Bid 2/13/08	Project 08-64 Incomplete run/Also see TV done 7/13/06 & 2/4/08
						Offset joint, med	13.9				
						Offset joint, med	23.9				
						Protruding tap	27.3				
						Offset joint	28.9				
						Offset joint	30.1				
						Offset joint	41.2				
						Offset joint	71.8				
						Offset joint	76.7				
						Offset joint	82.6				
						Offset joint, bad	92.6				
						Tap, right, OK	92.7				
						Silt buildup EOR	119.0				
						RIJ, lgt	3.5				
						Belly starts	24.0				
						RIJ	32.7				
						RIJ	38.8				
						AB tap, right, ok	51.6				
						Belly ends	57.9				
						AB tap, left, ok	60.0				
						Tap repaired,R, ok	65.0				
						AB tap, right, ok	97.8				
						Belly starts	100.9				
						RIJ, med	104.7				
						Tap, repaired,R, ok	144.1				
						RIJ, lgt	152.5				
						Belly ends	158.0				
						RIJ, med	158.5				
						RIJ, lgt	170.1				
						Dropped pipe	173.2				
						Belly starts	185.0				
						Needs to Jet	195.0				

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Town	Darby Hills Rd & Jefferson	96	10-63		10-31	Offset joint Offset joint Offset joint Tap, right, ok Offset joint Offset joint Offset joint Offset joint Offset joint/roots, lgt Offset joint/belly starts Offset joint/belly ends Offset joint Offset joint Offset joint Offset joint Offset joint Offset joint EOR	1.6 6.5 11.6 12.9 18.6 28.9 34.3 38.7 43.8 48.9 53.8 59.3 68.7 73.9 79.1 84.6 89.2 96.2	01/30/2008	Slipline		
Green Springs Valley	8477 Sycamore Dr	0	11-197		11-196	AB tap, right, ok Tap, left, ok Tap, left, ok Offset joint, lgt Offset joint, lgt Grease in pipe 1/2"	35.0 38.6 44.0 64.9 74.6 87.7	01/30/2008	Slipline		Re-entered 2/4/08
Green Springs Valley	8444 Sycamore Dr	216	11-209		11-210	Belly start Belly ends RIJ, med RIJ, lgt AB tap Tap, repaired, R, ok Tap, repaired, L, ok RIJ, lgt RIJ, lgt Tap, repaired, L, ok AB tap, left EOR	2.9 8.2 18.7 28.9 49.7 85.5 114.6 127.3 137.5 166.7 207.6 216.1	01/30/2008	Slipline		

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	4622 Elm Dr	422	11-215		11-216	RIJ, lgt, 4 jnts	4.1-18.4	02/04/2008	Slipline		Project 08-168
						Tap, right, ok	31.2		Point Repair		
						crack in 8" by tap	31.2				
						AB tap, right	99.4				
						RIJ, lgt, 4 jnts	145.6-165.7				
	4600 Elm Dr					Tap, right	174.3				Project 08-169
						RIJ, lgt, 2 jnts	176&181.1		Point Repair		
	4588 Elm Dr					RIJ, hvy	186.1				Project 08-170
						RIJ, lgt, 2 jnts	190.3&201.1				
	4566 Elm Dr					AB tap, right	207.1				Project 08-171
	4555 Elm Dr					RIJ, lgt, 2 jnts	208.1&218.0				Project 08-172
						AB tap, right	304.4		Repair tap & crack		
						Tap, right, offset&crack	325.2				
						Tap, left, ok	357.2				
						AB tap, right	414.5		Repair tap & crack		
						Tap, right, crack in line	416.6		Point repair at MH		
						MH, offset pipe	421.6				
Town	510 W Jennings	198	9-12		9-11	Offset jnt, med	7.0	02/04/2008	Slipline		Project 08-142
						tap, top, ok	7.9				
						Offset joint	8.8				
						Belly Start	8.8				
						Offset jnt, med, 2 jnts	13.5&23.4				
						Protruding tap, top	27.7				
						Offset jnt, med	29.1				
						AB tap, ok	29.8				
						Offset jnt, med, 10 jnts	30.4-81.0				
						Offset jnt	91.4				
						Tap, top, ok	92.7				
						Offset jnt, med, 7 jnts	93.7-133.7				
						Tap, top, ok	134.3				
						Offset jnt, med, 4 jnts	135.5-150.6				
						Tap, top, ok	151.6				
Offset jnt, med, 9 jnts	152.7-193.1										
Dropped pipe, severe	197.6		Repair dropped pipe	03/06/08	Project 08-30						

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8499 Sycamore	341	11-197		11-196	AB tap, right, ok	34.9	02/04/2008	Slipline		Project 08-173
	4588 Stonegate Dr (hse in Stonegate/line in back of house)					Tap, left, ok	38.5		Repair Tap		
						Offset joint, lgt	44.3				Project 08-174
						Offset joint, lgt	50.8				Also entered 1/30/08
						Offset joint, lgt	65.4				
						Offset joint, lgt	76.0				
						Tap, right,root/hvy	88.8				
						AB tap, right, ok	120.6				
						Tap, left, roots/hvy	141.5				
						Offset joint, lgt	337.1				
						MH 11-196	341.4				
Stonegate	8388 Stonegate	213	11-134		11-199	Offset Joint, lgt	15.4	02/04/2008	Slipline		Also entered 1/30/08
						Offset joint, lgt	32.4				
						Offset joint, lgt	38.5				
						Offset joint, lgt	44.7				
						AB tap, right, ok	51.7				
						Tap, left, ok	59.8				
						Offset joint, lgt	60.8				
						Tap, repaired, R, ok	64.5				
						AB tap, right, ok	97.9				
						Belly start	97.9				
						RIJ, lgt	104.6				
						Tap, repaired, R, ok	144.2				
						RIJ, lgt	152.0				
						RIJ, lgt	157.9				
						Offset joint, med	173.7				
						Offset joint, med	195.8				
Offset joint, med	206.6										
End of Belly	212.5										

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8288 Oak	142	11-228		11-210	Tap, right, ok Tap, left, ok AB tap, left Offset joint AB tap, right RIJ, lgt RIJ, lgt Offset joint RIJ, lgt RIJ, med Offset joint RIJ, lgt RIJ, med Tap, right, roots/med RIJ, lgt RIJ, med RIJ, lgt RIJ, med	46.7 49.1 78.1 78.4 80.5 81.4 86.2 91.1 96.1 101.1 106.2 110.7 116.7 121.9 122.8 132.6 137.6 141.7	02/07/2008	Repair Tap		Project 08-222
Green Springs Valley	8099 Chestnut	31	11-232		11-231	RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt RIJ, lgt RIJ, bad	1.3 6.9 11.4 16.1 21.5 26.7 31.4	02/07/2008	Slipline Redone for CEI Slipline		
Green Springs Valley	8277 Chestnut	88	11-235		11-234	Belly start Tap, repaired, ok	.5 87.7	02/08/2008	Slipline Redone for CEI Slipline		
Green Springs Valley	8088 N Larch	0	11-252		11-255	Belly starts at MH RIJ, med RIJ, med RIJ, med RIJ, lgt RIJ, lgt RIJ, med RIJ, med Rlj, lgt AB tap, left, root/lgt RIJ, med RIJ, lgt RIJ, lgt	9.2 11.8 15.7 20.8 26.0 30.9 36.1 37.4 48.4 53.0 63.3	02/08/2008	Slipline Redone for CEI Slipline		Also entered 2/19/08

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8400 Lincoln/ 8433 Chestnut	86	11-237		11-238	Tap, left, OK	1.2	02/11/2008	Repair tap		Project 08-191
						Offset joint light	3.1				
						AB tap, OK	3.6				
						Offset joint light	10.0				
						Offset joint light	14.0				
						Belly start	14.0				
						Offset joint light	24.3				
						AB tap, left	81.2				
						AB tap, right	83.6				
						Offset joint	84.3				
						Offset joint with tap, R	86.3				
						Green Springs Valley	8311 Birch Dr				
RIJ, lgt	10.4										
RIJ, lgt	15.1										
RIJ, med	19.7										
RIJ, lgt	35.6										
RIJ, lgt	40.9										
RIJ, lgt & OJM	45.7										
RIJ, lgt	50.6										
OJM & Belly stops	126.0										
OJM	131.1										
OJM	146.2										
OJM	150.8										
Belly starts	158.9										
OJM & Belly stops	175.6										
EOR	221.6										

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8277 N Larch Pl	427	11-249		11-261	Belly start	1.0	02/20/2008	Slipline		Project 08-192
						OJM	4.6				
	Roots, lgt	9.5&11.0									
	OJM	29.2&65.5									
	AB tap, left, OK	85.5									
	Belly start	119.6									
	LJ	130.1									
	Tap, left, OK	139.6									
	OJM	147.7									
	AB tap, OK	167.9									
	OJM	180.2									
	LJ	186.4									
	OJM	204.3&216.3									
	OJM	222.6&228.7									
	OJM	241.4									
	Belly stop & pipe crack	271.8									
	OJM	278.2									
	Tap, right, old rep. OK	281.8									
	OJM/cracked pipe, lgt	290.1									
	OJM	296.8&326.8									
	OJM/roots, lgt	338.4									
	OJM	344.2									
	AB tap, OK	346.2									
	RIJ, med	346.9									
	RIJ, med/Belly start	352.6									
	RIJ, bad	358.8									
	RIJ, bad	375.9									
	OJM/roots, med	399.1									
	OJM	424.3									
	EOR	427.4									

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Broadview B	8000 Meadow Ridgemont (need #) 8044 Meadow 8044 Meadow 8088 Meadow	387	15-211		15-277	OJ, lgt	15.6	02/20/2008	Repair tap (at 63.8')		Project 08-194
						Belly start	19.2				
						OJS	50.8				
						AB tap, right, ok	62.1				
						Tap, left, roots	63.8				
						OJM	79.3				
						LJ	89.6				
						OJM	94.3&99.7				
						OJM & LJ	104.9&114.8				
						OJM	120.0&125.2				
						OJM	130.0				
						Tap,R,old rep/8" line offset	144.0				
						OJM					
						AB tap, Right, ok	150.7&156.0				
						Tap, left, ok	163.0				
						OJM	165.0				
						OJM	170.1&185.1				
						OJM	190.4&195.8				
						OJM/LJ/roots,lgt	200.9&205.5				
						Start of old repair	220.7				
						Tap, right, ok	225.6				
						End of old repair/offset	323.7				
						jnt/med	251.8				
						RIJ, bad	257.0				
						OJM	267.8&272.0				
AB tap, right	279.2										
OJM	280.0										
Tap, left, roos/hvy	281.3										
OJM	287.1&291.5										
OJM	297.3&302.4										
OJM with roots	306.9										
OJM	312.1										
Belly starts/bad	313.6										
OJM	317.5										
OJM/bad belly stops	322.9										
OJM/old repair	339.0										
Tap, R, ok/old repair	340.0										
OJM/old repair	341.0										

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Green Springs Valley	8022 N Larch PI	429	11-255		11-252	RIJ, lgt	37.7	02/19/2008	Repair dropped pipe (47.9')		Project 08-199
	Drop pipe, fernco					47.9	Repair RIJ (possible tap at 414.3')		Project 08-200		
	8033 N. Larch PI					Tap, right, ok	53.0				
						Tap, left, ok	66.2				
						Offset joint, lgt	82.6				
						Tap, right, ok	138.5				
						Tap, left, ok	141.3				
						RIJ, lgt	151.5				
						AB tap, right, ok	228.0				
						Tap, left, ok	235.0				
						Offset joint, old repair	249.2				Also entered 2/8/08
						Tap, right, ok	251.5				
						Offset pipe	286.3				
						Tap, right, ok	292.7				
						AB tap, right, ok	302.7				
						Tap, left, ok	329.7				
						RIJ, lgt	361.9		Slipline		
						RIJ, med	376.5				
						AB tap, R, roots/med	387.3				
						RIJ, med	393.8				
						RIJ, med	408.6				
						RIJ/possible tap, roots	414.3				
						EOR	428.5				
South Broadview	5366 E Timberwood					Tap, top, maybe hammer	60.8	02/21/2008	Repair tap	Bid 2/26/08	Project 08-201
						Tap, top, ok	70.0				
						Belly starts	112.8				
						OJM	120.7				
						Belly stops	123.8				
						Tap, top, ok	126.2				
						Tap, top, ok	161.6				
						Belly starts	207.2				
						Belly stops	230.0				
						OJM	271.8				
						Tap, top, ok	274.5		Slipline		
						Belly start	278.5				
						Old repair, ok	281.5				
						OJM	302.2				
						OJM	314.6				
						Tap, right, ok	325.4				
	5322 E Timberwood	335	14-54		14-55	OJS	334.8	02/21/2008	Repair joint	5/2/08	Project 08-202

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Tennyson Terrace	7899 Owens Dr	223	15-51		15-50	RIJ, lgt OJM Start of repair Tap, right, ok End of repair OJM OJM OJM Tap, right, repaired ok AB tap, left, ok OJM AB tap, right ok RIJ, med RIJ, med Tap, top, ok RIJ, lgt & OJM RIJ, severe	28.6 58.7 63.0 66.4 68.5 73.2 83.4 108.5 162.0 170.7 171.2 173.0 178.3 188.4 206.7 213.5 223.2	02/21/2008	Slipline Re-TV to check if repair needed		
Heritage Place	6599 Heritage	243	21-51		21-50	Tap, right, ok Tap, top, ok Tap, right, ok Tap, right, roots, hv RIJ RIJ, med	68.1 120.6 145.5 222.5 251.1 243.0	02/25/2008	Slipline Repair Tap	2/29/08	Project 08-203
Springvale	6666 Springvale	51	21-59		20-167	Belly start Silt in pipe	23.1 51.3	02/25/2008	Need to jet & re-tv		
Springvale	6666 Springvale	15	21-59		21-60	MH 21-60	15	02/25/2008	OK	02/25/08	
Twin Oaks	7355 Oaklawn	38	15-172		15-123	MH 15-123	38.2	02/26/2008	OK	02/26/08	
Twin Oaks	7355 Oakdale Dr	144	15-117		15-124	OJM/LJ RIJ, lght, grease RIJ, med	1.1 133.4 143.8	02/26/2008	Partial/Jet flush		
Twin Oaks	7355 Oaklawn	0	15-124		15-122	OJM Tap, right, Protruding	5.0 6.6	02/26/2008	Repair Tap	02/27/08	Project 08-204 See below and 2/28/08
Twin Oaks	7411 Oaklawn	0	15-122		15-124	Tap, protruding	2	02/26/2008	Repair Tap		Project 08-206 See above and 2/28/08

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Tennyson Terrace	7922 Lincoln Ave in back of house	313	15-59		15-58	Tap, left, ok LJ, right Belly start RIJ, lgt w/LJ, lgt OJM Tap, right, ok RIJ, med LJ, lgt Tap, left, ok Tap, roots, lgt Tap, right, ok AB tap, left Tap, right, ok Tap, protruding, left MH 15-58	17.3 25.0 28.0 104.4 109.6 111.0 122.0 161.3 193.0 228.4 255.4 302.8 304.7 306.9 313.0	02/27/2008	Slipline Repair tap		Project 08-207
Twin Oaks	7344 Oakdale 7377 Oaklawn 7366 Oakdale 7377 Oaklawn	137	15-124		15-122	Tap, right, OK Tap, left, roots Hammer tap, right Hammer tap, L top, rts Roots jnt, hvy (problem)	7.5 52.2 94.5 117.2 136.7	02/28/2008	Repair tap Repair tap Repair tap Repair problem (WB &/or RP need to look at DVD)	Pending Pending Pending Bid 2/26/08	Project 08-210 Project 08-211 Project 08-212 Project 08-208 Also entered 2 time 2/26/08
Sunrise Manor	4822 Hwy 261 8141 Alexandria (compl)	11	11-283		11-192	Separated joint Separated joint Separated joint MH 11-192	1.0 4.7 10.1 10.7	02/29/2008	8" Main line replacement &/or Slipline		TV Only/Not Jetted Project 08-216
Broadview	7633 Meadow	80	15-177		15-176	Tap, left, OK Tap, right, OK Offset joint, severe	67.2 79.6 80.3	03/04/2008	Point repair	03/14/08	Project 08-213
Tennyson Terrace	7766 Owens Dr Betw 7800/7822 Owens	425	15-37		15-36	Point repair, OK Tap, left, roots, lgt Tap, left, OK Tap, left, OK Tap, left, OK Tap, left, roots, lgt Tap, right, OK Tap, left, OK Tap, left, OK MH 15-36	20.1 35.7 63.7 120.5 234.7 310.4 344.7 349.3 412.9 425.1	03/04/2008	Repair Tap Repair Tap		Project 08-214 Project 08-215

<div style="display: flex; justify-content: space-between; font-size: small;"> (Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair </div>											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Heritage Place	6577 Heritage Dr					Tap, right, ok	69.2	03/05/2008	Repair tap		Project 08-217
	Tap, top, ok					122.1					
						Tap, right, offset	146.2				
						Tap, right, ok/old repair	222.8				
						RIJ, Lgt, LJ at top	253.9				
						RIJ, lgt	268.4				
						RIJ, med	274.5				
						RIJ, lgt	278.7				
						RIJ, med	283.6				
						RIJ, lgt	288.8				
Heritage Place	6610 Heritage Dr	294	21-54		21-55	Offset old repair/severe	293.9	03/05/2008	Point repair		Project 08-218
Green Springs Valley	4366 W Larch (Inv as 4399 W Larch Pl (Complaint/8133 N Larch)	12	11-266		11-267	RIJ, med	2.5	03/10/2008	Install MH	03/17/08	See entry below Project 08-85
						RIJ, lgt	7.3				
						RIJ, lgt	12.3				
						Elbow to left	12.3				
Green Springs Valley	8155 N Larch (Complaint/8133 N Larch)	224	11-267		11-266	Damaged area	224	03/10/2008	Repair damaged area after MH installed above		See entry above Project 08-221
Kingston Eastbrook	3233 Brookfield Dr	284	16-99		16-103	Tap, left, ok	81.0	03/10/2008	Slipline		
						RIJ, lgt	173.4				
						RIJ, lgt	183.6				
						Tap, left, ok	222.4				
						Belly start	268.5				
						Belly stops	283.8				
						MH 16-103	283.8				
Ridgewood	6522 Hemlock Way	0	20-49		20-50			03/10/2008	Need to jet & re-tv On Slipline		
Springvale	6600 Valley Rd	135	20-150		20-149	Belly start	0.0	03/10/2008	On Slipline		
						Belly stops	37.6				
						AB tap, left, ok	90.2				
						AB tap, right ok	97.4				
						Belly start	102.1				
						Tap, top, ok	111.8				
						Tap, top, ok	114.2				
						RIJ, lgt	123.3				
						AB tap, right ok	124.5				
						RIJ, lgt	132.5				
						RIJ, lgt	135.3				
						Green Springs Valley	8333 Chestnut Dr				

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Springvale	6588 Center Ridge	254	20-162		20-163	LJ, med	4.2	03/14/2008	On Slipline	Bid 2/22/08	Project 08-91
						AB tap, right, clay	46.1				
	RIJ, lgt					47.4	Repair Tap				
	RIJ, med, L/lgt					62.2					
	RIJ, lgt					72.2					
	RIJ, lgt					91.2					
	Tap, left, roots, hvy					97.8					
	AB tap, left, clay					100.0					
	RIJ, lgt					110.4					
	RIJ, lgt					125.4					
RIJ, lgt	143.5	Repair Tap									
Tap, left, OK (rep PVC)	143.5										
RIJ, lgt	150.1										
Tap, right, roots/hvy, clay	156.4										
RIJ, lgt	191.9										
RIJ, lgt	202.2										
LJ, lgt	216.8										
Tap, right, roots/hvy	224.1	Repair Tap									
AB tap, OK, clay	253.4										
PT, left, roots/hvy(2-3")	254.4	Repair Tap									
Heritage Place III	6700 Valley Rd	28	20-172		20-171	LJ, lgt	16.2	03/17/2008	Repair tap	7/16/08	Project 08-223
						LJ, lgt	21.7				
						PT, left at 11:00/PVC	27.6				

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplin (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Broadview B	4600 Broadview Dr (complaint 7677 Broadview)	393	15-187		15-188	AB Tap, L, clay ok Tap, R, pvc ok Tap, left, pvc ok Offset jnt, clay-truss, med Tap, R, ok Offset jnt, truss-clay, rep'd AB tap, L, ok AB tap, R, ok Tap, L, pvc, ok 3" crk betw clay & new rep Tap, R, pvc, ok AB tap, L, clay ok AB tap, R, clay ok Tap, left, ok Cty-tru/rep'd/offset 1 1/2" Tap, R, truss offs ins tap PVC RIJ, lgt RIJ, lgt MH 15-188	56.1 58.5 63.8 158.4 161.8 168.1 225.1 226.7 255.8 277.1 279.3 324.6 326.6 349.1 361.8 365.3 372.6 382.5 393.2	03/17/2008	3" crack at 277.1' is at a Stemaly repair (Wayne will discuss with Leon) Re-TV done 5/22/08 - shows OK	05/22/08	Also see 5/22/08
Heritage Place III	Need address (Jamestown)	112	20-147		20-172	Tap, top, ok, clay Hammer tap, top, right Belly start Belly end	25.5 93.5 93.5 112.3	03/17/2008	Repair Tap		Project 08-224
Busler's/Pine Dr	Need address (Pine Dr) Need address (Pine Dr)	162	15-223		15-225	Tap, right, ok RIJ, lgt RIJ, lgt, leak sm drops RIJ, med, leak steady stream Hammer tap, R, PVC (no leak, prot, or offsets) Hammer tap, R, PVC (no leak, prot, or offsets) Jnt, sm sep, steady stream from top AB tap, right, ok EOR	26.5 32.9 77.4 87.7 89.9 91.7 117.6 124.9 162.3	03/18/2008	Repair Tap Repair Tap Put on Slipline		Project 08-225 Project 08-226
Busler's/Pine Dr	Walgreens	266	15-223		15-224	EOR	266.2	03/18/2008	ok	03/18/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Newburgh Plaza South	8077 Rose Hill Dr	245	10-148		10-151	LJ Belly start Belly ends AB tap, right, ok, clay AB tap, left, ok, clay Belly start PT, 1" top, ok Belly ends Tap, top, ok PVC AB tap, left, ok, caly AB tap, right, ok, clay PT, 11:00, PVC, 2-3"	9.6 68.1 84.2 91.9 94.1 147.9 151.3 158.9 174.8 191.9 193.4 245.0	03/24/2008	NSD to Repair tap		
Town/Fosters	724 Cypress	328	10-108		10-107	OJM Belly start Old repair/Truss start end of repair/offset jnt RIJ, lgt AB tap, L,leak,roots/lgt Belly ends Belly starts New repair/starts,truss Tap, top,ok, new rep. Old repair, truss Tap, L, offset 1"&leaking End of old repair AB tap, ok MH 10-107	26.5 35.0 36.1 43.7 77.9 128.4 159.2 170.0 179.6 181.4 223.6 226.8 232.9 306.6 327.9	03/24/2008	Slipline		
Lexington Development	Corner of Sable Ridge & Essex Dr	317	26-49		26-50	Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss Tap, left, OK, truss MH 26-50	15.3 32.8 127.1 222.9 311.6 317.4	03/31/2008	ok	03/31/08	
Lexington Development	Corner of Sable Ridge & Essex Dr	0	26-49		26-44	Tap, left, ok, truss Tap, right, ok truss Tap, left, ok, truss MH 26-44	139.4 140.8 226.8 238.2	03/31/2008	ok	03/31/08	See TV done 5/14/08
Lexington Development	Corner of Sable Ridge & Ashley Dr	80	26-57		26-56	Pipe separated 6-8" MH 26-56	73.8 79.8	04/02/2008	Repair main		

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Blue Lake	2988 Briarcliff	133	22-01		22-02	Tap, R, ok Tap, L, ok Tap, Top, ok Tap, L, ok Tap, L, ok	1.6 5.3 37.5 127.3 132.6	04/08/2008	Incomplete		
WWTP	Effluent Overflow at plant	385				Belly Begins End of pipe (open end into creek)	358.4 385.2	05/08/2008	ok	05/08/08	TV only
Lexington Development	Sable Ridge	198	26-57		26-58	Tap, L, PVC, ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-58	16.6 92.9 119.1 191.8 198.0	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	97	26-57		26-59	MH 26-59	96.7	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	159	26-59		26-60	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 26-60	13.2 85.4 151.1 159.1	05/12/2008	ok	05/12/08	
Lexington Development	Corner of Sable Ridge & Thornbury Circle	112	26-59		26-61	Tap, R, PVC ok MH 26-61	90.8 111.6	05/12/2008	ok	05/12/08	
Lexington Development	Sable Ridge	87	26-61		26-65	Tap, R, PVC ok MH 26-65	55.6 86.7	05/12/2008	ok	05/12/08	
Warrick Place	Apple Center	22	16-113		?	EOR	22.1	05/13/2008	ok	05/13/08	
Lexington Development	Sable Ridge	280	26-61		26-62	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-62	81.7 106.5 168.8 271.6 280.1	05/13/2008	ok	05/13/08	
Lexington Development	Oak Park Dr	93	26-62		26-63	Tap, R, PVC ok MH 26-63	78.8 92.9	05/13/2008	ok	05/13/08	
Lexington Development	Oak Park Dr	73	26-63		26-64	Tap, R, PVC ok MH 26-64	65.0 73.0	05/13/2008	ok	05/13/08	
Lexington Development	Ashley Dr & Sable Ridge	170	26-56		26-52	Tap, R, PVC ok Tap, R, PVC ok MH 26-52	43.2 142.0 170.0	05/13/2008	ok	05/13/08	
Lexington Development	Corner Ashford & Ashley	239	26-53		26-52	Tap, top, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 26-52	143.5 145.5 225.3 238.7	05/13/2008	ok	05/13/08	
Lexington Development		55	26-53		26-55	Tap, L, PVC ok MH 26-55	48.6 55.0	05/14/2008	ok	05/14/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Lexington Development	Ashford Dr	47	26-53		26-54	Tap, R, PVC ok Tap, R, PVC ok MH 26-54	4.4 38.6 46.5	05/14/2008	ok	05/14/08	
Lexington Development		133	26-42		26-43	Tap, L, PVC ok Tap, L, PVC ok MH 26-43	46.6 126.5 133.0	05/14/2008	ok	05/14/08	
Lexington Development		254	26-42		26-44	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-44	91.1 147.8 179.1 253.7	05/14/2008	ok	05/14/08	
Lexington Development		143	26-42		26-41	Tap, R, PVC ok Tap, R, PVC ok MH 26-41	38.6 127.6 143.1	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	58	26-51		26-44	MH 26-45	58.4	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	282	26-51		26-52	Tap, L, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 26-52	18.2 19.9 129.1 133.9 282.3	05/14/2008	ok	05/14/08	
Lexington Development	Essex Dr	239	26-44		26-49	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-49	8.1 93.9 94.8 238.9	05/14/2008	ok	05/14/08	Also see TV done 3/31/08
Lexington Development	Essex Dr	101	26-44		26-45	MH 26-45	100.7	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	41	26-46		26-45	MH 26-45	40.7	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	176	26-46		26-47	Tap, R, PVC ok MH 26-47	30.5 175.6	05/14/2008	ok	05/14/08	
Lexington Development	Lenox Dr	170	26-47		26-48	Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 26-48	15.2 115.0 114.2 120.1	05/14/2008	ok	05/14/08	
Lexington Development	Glenview Dr	110	26-41		26-40	MH 26-40	109.7	05/14/2008	ok	05/14/08	
Lexington Development		160	26-39		26-40	MH 26-40	159.9	05/15/2008	ok	05/15/08	
Lexington Development		91	26-39		26-38	MH 26-38	91.0	05/15/2008	ok	05/15/08	
Lexington Development		272	26-28		26-38	Tap, L, PVC ok MH 26-38	175.8 272.1	05/15/2008	ok	05/15/08	
Lexington Development		124	26-28		26-27	MH 26-27	124.2	05/15/2008	ok	05/15/08	
Lexington Development		191	26-28		26-29	Tap, R, PVC ok Tap, R, PVC ok MH 26-29	35.8 130.1 191.2	05/15/2008	ok	05/15/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Lexington Development		222	26-31		26-29	Tap, L, PVC ok Tap, L, PVC ok MH 26-29	58.0 159.5 221.9	05/15/2008	ok	05/15/08	
Lexington Development		225	26-31		26-33	Tap, top, PVC ok Tap, R, PVC ok MH 26-33	61.8 162.2 224.5	05/15/2008	ok	05/15/08	
Lexington Development		215	26-33		26-34	Tap, R, PVC ok Tap, L, PVC ok MH 26-34	106.8 179.0 214.7	05/15/2008	ok	05/15/08	
Lexington Development		203	26-33		26-35	Tap, R, PVC ok Tap, R, PVC ok MH 26-35	57.8 153.5 202.6	05/15/2008	ok	05/15/08	
Lexington Development		213	26-35		26-36	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 26-36	100.1 105.2 200.0 213.1	05/15/2008	ok	05/15/08	
Lexington Development		200	26-35		26-37	Belly End belly Tap, R, PVC ok Tap, R, PVC ok MH 26-37	6.0 17.0 143.8 194.0 200.3	05/15/2008	ok	05/15/08	
Huntington Ridge	4378 Huntington Ridge Ct	104	07-161		07-162	Tap, L, PVC ok Tap, R, PVC ok MH 7-162	69.4 75.9 104.2	05/16/2008	ok	05/16/08	Also see 5/19/08
Huntington Ridge	4378 Huntington Ridge Ct	238	07-161		07-59	MH 7-59	237.5	05/16/2008	ok	05/16/08	
Huntington Ridge	4338 Huntington Ridge Ct	239	07-163		07-162	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-162	9.6 57.1 122.8 238.7	05/16/2008	ok	05/16/08	
Huntington Ridge	4338 Huntington Ridge Ct	234	07-163		07-164	Tap, R, PVC ok Tap, R, PVC ok MH 07-164	73.8 163.2 233.6	05/16/2008	ok	05/16/08	
Huntington Ridge		251	07-165		07-166	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 7-166	57.7 135.1 218.1 244.4 250.8	05/16/2008	ok	05/16/08	
Huntington Ridge	4378 Huntington Ridge Ct	0	07-162		07-161	Tap, L, PVC ok Tap, R, PVC ok MH 7-161	24.2 31.4 104.9	05/19/2008	ok	05/19/08	Also see 5/16/08
Huntington Ridge	4378 Huntington Ridge Ct	9	07-162		07-168	MH 7-168	9.0	05/19/2008	ok	05/19/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Huntington Ridge	4378 Huntington Ridge Ct	333	07-168		07-167	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, R, PVC ok MH 7-167	99.6 151.8 189.8 254.5 261.2 324.7 326.0 332.9	05/19/2008	ok	05/19/08	
Huntington Ridge	4378 Huntington Ridge Ct	292	07-168		07-169	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-169	99.1 177.2 254.7 291.5	05/19/2008	ok	05/19/08	
Huntington Ridge	4228 Huntington Ridge Ct	296	07-170		07-171	Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 7-171	31.9 56.1 110.8 124.6 189.2 202.9 290.0 295.6	05/19/2008	ok	05/19/08	
Huntington Ridge	4228 Huntington Ridge Ct	221	07-170		07-169	Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-169	48.4 63.8 138.5 220.9	05/19/2008	ok	05/19/08	
Town	Monroe St. between 3rd & 4th streets (Complaint address)	190	10-80		10-83	Belly start Belly ends Belly start Belly ends Tap, right Belly stops Blown gasket	18.9 45.8 68.9 77.1 87.4 160.0 189.8	05/19/2008	Emergency Main LineRepair	5/23/08	Complaint 5/19/08 Project 08-242 TV Only/Not Jetted
Town	Monroe St. between 3rd & 4th streets (Complaint address)	48	10-83		10-80	Belly start Problem	0.0 47.7	05/19/2008	Emergency Repair Same as above	5/23/08	Complaint 5/19/08 Project 08-242 TV Only/Not Jetted
Huntington Ridge		292	07-172		7-169	Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok MH 7-169	18.7 96.6 174.3 251.9 291.5	05/19/2008	ok	05/19/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Huntington Ridge	9311 Emily Ct	381	07-173		07-174	Tap, R, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, L, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, R, PVC ok Tap, L, PVC ok MH 07-174	22.8 36.4 101.5 115.6 182.6 194.2 272.6 285.7 370.4 374.4 381.4	05/20/2008	ok	05/20/08	
Huntington Ridge	9311 Emily Ct	137	07-173		07-172	Tap, L, PVC ok Tap, R, PVC ok MH 07-172	42.0 46.5 136.8	05/20/2008	ok	05/20/08	
Huntington Ridge	9299 Millicent Ct	378	07-176		07-177	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-177	20.9 98.9 163.7 255.2 332.6 360.1 377.7	05/20/2008	ok	05/20/08	
Huntington Ridge	9299 Millicent Ct	69	07-176		07-175	MH 07-175	69.0	05/20/2008	ok	05/20/08	
Huntington Ridge		179	07-175		07-172	Tap, R, PVC ok Tap, R, PVC ok MH 07-172	43.0 120.6 179.4	05/20/2008	ok	05/20/08	
Huntington Ridge		73	07-175		07-178	Tap, L, PVC ok Tap, L, PVC ok MH 07-178	23.2 68.1 73.4	05/20/2008	ok	05/20/08	
Fieldcrest Place		53	07-131		07-130	Tap, R, PVC ok Tap, R, PVC ok MH 07-130	7.1 48.5 52.7	05/20/2008	ok	05/20/08	
Fieldcrest Place		139	07-131		07-126	Tap, L, PVC ok MH 07-126	75.6 138.6	05/20/2008	ok	05/20/08	
Fieldcrest Place		312	07-125		07-124	Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok Tap, L, PVC ok MH 07-124	34.0 120.4 194.5 277.0 311.5	05/20/2008	ok	05/20/08	
Fieldcrest Place		263	07-125		07-126	Tap, L, PVC ok Tap, L, PVC ok MH 07-126	15.2 253.8 262.6	05/20/2008	ok	05/20/08	
Fieldcrest Place		282	07-125		07-132	MH 07-132	281.6	05/20/2008	ok	05/20/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fieldcrest Place	Empty Lot	162	07-123		07-122	Tap, L, ok Tap, L, ok Tap, L, ok MH 07-122	32.0 114.5 156.0 162.3	05/21/2008	ok	05/21/08	
Fieldcrest Place	Empty Lot	387	07-123		07-124	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 07-124	36.4 113.6 191.7 273.3 351.8 386.9	05/21/2008	ok	05/21/08	
Fieldcrest Place	Empty Lot	208	07-127		07-126	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 07-126	28.0 31.2 100.2 103.2 173.0 174.7 208.0	05/21/2008	ok	05/21/08	
Fieldcrest Place	Empty Lot	359	07-127		07-128	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 07-126	31.2 33.2 108.5 111.4 243.2 248.2 322.2 324.3 359.0	05/21/2008	ok	05/21/08	
Fieldcrest Place	4550 Fieldcrest Place	218	07-128		07-129	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 07-129	28.8 32.4 100.7 104.4 175.2 178.8 211.2 217.7	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	73	07-159		07-158	Tap, L, ok Tap, L, ok MH 07-158	62.6 65.7 72.6	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	44	07-159		07-160	Tap, R, ok MH 07-160	38.9 44.0	05/21/2008	ok	05/21/08	
Blackberry Hill	Empty Lot	82	07-158		07-156	MH 07-156	82.0	05/21/2008	ok	05/21/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Blackberry Hill	Empty Lot	110	07-156		07-157	Tap, R, ok Tap, R, ok MH 07-157	9.8 103.4 110.4	05/21/2008	ok	05/21/08	
						AB Tap, L, ok Tap, R, ok Tap, left, ok Pipe repair ok Pipe repair ok 1/4" Offset, clay-truss Tap, R, ok Tap, L, ok 1/4" Offset, truss-clay AB tap, L, ok AB tap, R, ok Tap, L, ok 1/4" offset, clay-truss Tap, R, ok 1/8" offset, clay-truss AB tap, L, ok AB tap, R, ok 1/4" offset Tap, L, ok clay-truss 1/8" offset, all truss 1/4" offset, clay-truss 1/8" offset, truss-clay MH 15-188	54.0 56.4 61.4 135.5 152.5 154.9 158.3 165.3 165.5 221.8 223.8 252.2 272.2 275.5 276.6 321.2 323.2 345.3 346.1 350.1 357.9 362.8 391.8	05/22/2008	ok	05/22/08	Also see 3/17/08
Broadview B	4600 Pine Dr	0	15-187		15-188						
Blackberry Hill		83	07-155		07-156	Tap, R ok MH 07-156	5.9 83.0	05/22/2008	ok	05/22/08	
Blackberry Hill		214	07-155		07-154	Tap, R, ok MH 07-154	180.9 213.8	05/22/2008	ok	05/22/08	
Fall Creek	Pemrose Dr (empty lot)	309	03-150		03-149	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok 1/4" offset, truss-truss Tap, R, ok MH 03-149	24.7 87.3 146.2 209.6 269.6 275.6 304.1 309.0	05/22/2008	ok	05/22/08	
Fall Creek	4751 Pemrose Dr	0	03-155		03-116	Belly starts	23.0	05/23/2008	Need to Jet & Re-TV	Re Jet done 6/12/2008	Re-TV done 6/12/08

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Pemrose Dr (empty lot)	362	03-151		03-150	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-150	24.0 85.3 148.9 209.8 269.2 333.6 362.0	05/23/2008	ok	05/23/08	
Fall Creek	Pemrose Dr (empty lot)	249	03-151		03-152	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-152	35.1 97.8 157.7 217.1 249.0	05/23/2008	ok	05/23/08	
Fall Creek	Pemrose Dr (empty lot)	77	03-153		03-152	Tap, R, ok Tap, R, ok MH 03-152	9.4 67.0 76.5	05/23/2008	ok	05/23/08	
Fall Creek	Pemrose Dr (empty lot)	114	03-153		03-154	Tap, L, ok Tap, L, ok MH 03-154	31.7 90.9 113.9	05/23/2008	ok	05/23/08	
Fall Creek	4763 Pemrose Dr	368	03-154		03-156	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-156	80.4 85.5 148.0 153.1 209.5 215.1 272.2 277.9 336.5 341.0 367.9	05/23/2008	ok	05/23/08	
Fall Creek	4757 Pemrose Dr	119	03-159		03-154	Tap, R, ok Tap, R, ok MH 03-154	22.0 84.0 119.0	05/23/2008	ok	05/23/08	
Fall Creek	4757 Pemrose Dr	34	03-159		03-155	MH 03-155	33.9	05/23/2008	ok	05/23/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	308	03-157		03-156	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Belly start 1" MH 03-156	25.6 30.0 86.1 91.7 146.4 151.9 209.5 213.6 275.6 280.2 305.0 307.6	05/27/2008	ok	05/27/08	
Fall Creek	Empty Lot	253	03-157		03-158	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-158	22.2 26.9 83.6 88.0 144.5 149.2 210.5 215.6 245.4 248.5 252.6	05/27/2008	ok	05/27/08	
Fall Creek	Empty Lot	372	03-148		03-146	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-147	34.6 94.6 156.3 215.7 280.0 341.0 371.9	05/27/2008	ok	05/27/08	
Town	Corner Fourth & Monroe	67	10-80		10-78	RIJ, Hvy	66.8	05/27/2007	ok	05/27/08	Done to help Street Dept. TV only/Not Jetted
Royal Highlands	5511 Lakeside Dr	0	Royal Sta		20-97	Roots & grease	44.6 ??	05/27/2008	Repair tap Repair joint	6/2/08 5/29/08	Project 08-243 Project 08-246
Royal Highlands	5533 Lakeside Dr	0	Royal Sta		20-97	RIJ, Hvy	60.1	05/28/2008	Point repair	Done with Proj. 08-243 & 246	Project 08-245
Royal Highlands	5533 Lakeside Dr 5533 Lakeside Dr	149	20-97		Royal Sta	Tap, R, roots hvy RIJ, hvy	72.1 88.4	05/28/2008	Repair tap Point Repair	Done with Proj. 08-243 & 246	Project 08-244 Project 08-245

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	10658 Fall Creek	392	03-125		03-126	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Crack in pipe Tap, R, ok Tap, L, ok MH 03-126	96.3 100.4 159.3 163.9 225.8 229.3 290.0 294.7 308.0 355.8 361.1 392.1	05/29/2008	Point repair	7/31/08	Project 08-247
Fall Creek	10730 Fall Creek	286	03-125		03-122	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 03-122	66.4 71.4 227.6 231.2 285.8	05/29/2008	ok	05/29/08	
Fall Creek	10730 Fall Creek	284	03-125		03-128	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-128	52.0 55.7 218.9 223.2 277.1 283.6	05/29/2008	ok	05/29/08	
Fall Creek	Empty Lot	386	03-144		03-116	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-116	12.6 16.9 77.6 81.7 136.9 141.9 194.4 199.5 259.9 264.5 317. 322.5 386.4	06/03/2008	ok	06/03/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	388	03-144		03-145	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-145	34.7 158.2 155.3 209.9 217.9 269.8 274.6 331.5 338.1 388.0	06/03/2008	ok	06/03/08	
Fall Creek	10542 Titan Dr	386	03-120		03-121	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-121	.8 1.2 33.0 38.5 93.1 98.1 160.0 165.2 222.6 227.4 287.9 292.8 352.8 358.2 386.4	06/04/2008	ok	06/04/08	
Fall Creek	Empty Lot	113	03-146		03-147	Tap, R, ok Tap, R, ok MH 03-147	82.0 108.4 113.1	06/04/2008	ok	06/04/08	
Fall Creek	Empty Lot	308	03-145		03-146	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Mud in pipe MH 03-146	23.5 26.6 82.2 84.9 143.2 146.1 210.2 212.4 298.3 308.3	06/04/2008	ok	06/04/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	10630 Titan Dr	382	03-121		03-122	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-122	24.5 29.5 89.7 94.4 156.2 159.0 218.5 226.9 283.9 288.1 382.2	06/05/2008	ok	06/05/08	
Fall Creek	10542 Fall Creek Dr	392	03-127		03-126	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-126	7.4 35.3 39.1 98.8 103.6 164.5 169.6 229.8 234.7 293.7 298.2 358.1 363.3 392.3	06/05/2008	ok	06/05/08	
Fall Creek	4808 Marble Dr	173	03-118		03-92	Tap, R, ok Tap, R, ok Tap, R, ok MH 03-92	26.6 85.0 145.6 172.9	06/05/2008	ok	06/05/08	
Fall Creek	4808 Marble Dr	367	03-118		03-119	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-119	19.3 28.3 142.9 202.1 265.5 324.4 360.9 366.8	06/05/2008	ok	06/05/08	
Fall Creek	4892 Marble Dr	109	03-131		03-130	Tap, R, ok Tap, L, ok MH 03-130	84.0 89.3 109.4	06/05/2008	ok	06/05/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Marble Dr	324	03-131		03-132	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-132	1.4 38.7 111.6 160.1 215.2 282.1 315.8 323.8	06/05/2008	ok	06/05/08	
Fall Creek	Empty Lot	378	03-129		03-128	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Left side wall is 1/4" Tap, L, ok MH 03-128	24.7 29.9 88.4 93.6 151.8 156.7 217.5 224.4 280.6 285.1 342.1 348.4 377.9	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	389	03-129		03-130	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, pipe leaking Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-130	24.5 29.1 89.6 94.5 151.5 151.5 156.1 215.7 220.0 282.1 287.1 344.1 348.3 389.3	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	35	03-137		03-136	Tap, R, ok Tap, R, ok MH 03-136	1.0 25.0 35.3	06/06/2008	ok	06/06/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	151	03-136		03-135	Offset Jnt, 1/2" Tap, R, mud Tap, L ok Tap, L, ok MH 03-135	48.4 100.9 105.7 146.7 151.0	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	81	03-136		03-138	Tap, R, ok Belly start Belly end MH 03-138	24.6 75.6 80.9 80.9	06/06/2008	ok	06/06/08	
Fall Creek	10627 Tecumseh	302	03-141		03-138	Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok Tap, L, ok MH 03-138	25.9 84.6 147.9 208.8 272.3 302.0	06/06/2008	ok	06/06/08	
Fall Creek	10627 Tecumseh	312	03-141		03-142	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-142	24.5 84.4 146.7 207.6 268.7 306.9 311.6	06/06/2008	ok	06/06/08	
Fall Creek	Empty Lot	403	03-134		03-133	Belly start 1 1/2" Belly stop Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Pipe 1/2 full of mud MH 03-137	0.0 18.5 20.5 25.5 86.0 90.2 148.9 153.9 214.5 220.4 279.5 283.4 343.4 349.2 383.2 386.1 397.0 402.6	06/09/2008	ok	06/09/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Fall Creek	Empty Lot	381	03-134		03-135	Belly start 1 1/2" Belly stop Tap, R, ok Tap, L, ok Tap, R, ok 1/3 mud Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok 1/2 mud Tap, R, ok MH 03-135	0.0 15.2 27.0 31.8 93.1 96.0 154.4 160.2 220.7 226.2 283.0 288.4 356.0 381.1	06/09/2008	ok	06/09/08	
ITT	10999 ITT Technical Inst.	22	04-11		ITT LS	ITT L.S.	21.6	06/09/2008	ok	06/09/08	
ITT	10999 ITT Technical Inst.	146	04-11		04-10	Belly start 1 1/2" Offset Jnt, 1/4" Belly stop MH 04-10	21.5 43.1 77.0 145.5	06/09/2008	ok	06/09/08	
County	Stahl Road	384	04-09		04-08	MH 04-08	384.2	06/09/2008	ok	06/09/08	
County	Stahl Road	0	04-09		04-10	Belly start Water over camera 1/2" pipe	10.2 34.9	06/09/2008	Jet & Re-Tv done 6/16/08	06/16/08	
County	Stahl Road	372	04-07		04-08	MH 04-08	371.9	06/09/2008	ok	06/09/08	
Springston	8111 Covington Ct	265	12-24		12-79	Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok MH 12-79	2.5 13.8 39.9 102.9 143.0 213.4 264.5	06/12/2008	ok	06/12/08	
Fall Creek	4751 Pemrose Dr	72	03-155		03-116	Belly start 1/3 of pipe Tap, L, ok Belly stops MH 03-116	68.0 71.9 135.0 135.0	06/12/2008	Main Line Repair List		Partial TV done on 5/23/08 Project #08-248

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) slipline (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Twin Oaks	7433 Oaklawn Dr	325	15-121		15-122	RIJ, med RIJ, lgt Cracked pipe, roots/lgt Tap, R, ok Tap, L, ok Tap, top, ok RIJ, lgt Cracked pipe, roots/lgt RIJ, lgt Sign of new repair Tap, L, ok End new repair RIJ, hvy RIJ, hvy New repair Tap, R End of new repair Tap, L, roots, hvy offset joint, small MH 15-122	46.3 52.8 89.5 90.6 95.3 103.3 167.8 177.2 180.1 190.6 191.3 196.0 218.0 223.0 246.7 250.0 258.0 272.0 303.2 325.2	06/16/2008	On Slipline List Root cut TV was also done 11/14/07 & 4 repairs were put on repair list (Wayne will review DVD)		Project 08-157 Project 08-158 Project 08-159 Project 08-160 (Repairs from the 11/14/07 Tv done)
Venetian Way	Stahl Road	42	04-09		04-10	MH 04-10	42.0	06/16/2008	ok	06/16/08	Also see 6/9/08
Venetian Way	Stahl Road	347	04-06		04-07	Tap, L, ok Tap, L, ok MH 04-07	.2 340.2 346.8	06/16/2008	ok	06/16/08	
Venetian Way	Stahl Road	307	04-06		04-05	MH 04-05	306.6	06/16/2008	ok	06/16/08	
Venetian Way	Lateral @ Oncology Hematology (3699 Epworth)	328	04-04		04-05	Tap, L, ok Joint in flow Tap, R, ok MH 04-05	159.0 184.7 198.3 327.8	06/16/2008	Contractor to investigate	10/13/08	Project 08-260
Venetian Way		274	04-03		04-04	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok MH 04-04	42.7 92.0 96.4 139.4 239.7 274.0	06/17/2008	ok	06/17/08	
Venetian Way		289	04-03		04-02	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 04-02	42.5 48.0 138.9 186.7 190.0 238.6 289.2	06/17/2008	ok	06/17/08	

<div style="display: flex; justify-content: space-between; font-size: small; margin-bottom: 5px;"> (Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair </div>											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Venetian Way		271	04-02		04-01	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 04-01	42.1 46.1 142.5 251.5 265.7 270.6	06/17/2008	ok	06/17/08	
Arbor Pointe		285	08-29		08-28	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 08-28	97.0 117.0 259.5 274.8 284.6	06/17/2008	ok	06/17/08	
Arbor Pointe		390	08-30		08-29	Tap, R, PVC ok Trap, L, pvc, ok Crack in pipe, RC Tap, R, pvc, ok Tap, L, pvc, ok Tap, R, pvc, ok MH 08-29	66.4 71.0 84.4 215.2 262.4 352.5 389.9	06/17/2008	Leon to review what should be done		
Arbor Pointe		208	08-30		08-31	MH 08-31	207.6	06/17/2008	ok	06/17/08	
Arbor Pointe		106	08-35		08-33	Tap, R, pvc ok Tap, R, pvc ok MH 08-33	94.3 98.8 105.7	06/17/2008	ok	06/17/08	
Arbor Pointe		139	08-35		08-34	Tap, R, pvc ok Tap, R, pvc ok MH 08-34	62.9 131.8 138.7	06/17/2008	ok	06/17/08	
Arbor Pointe		108	08-36		08-37	Tap, R, ok Tap, R, ok MH 08-37	37.1 103.5 108.4	06/18/2008	ok	06/18/08	
Arbor Pointe		258	08-39		08-40	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 08-40	40.7 97.1 100.2 143.1 257.6	06/18/2008	ok	06/18/08	
Arbor Pointe		288	08-39		08-38	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 08-38	34.1 39.0 141.0 185.6 189.2 238.6 287.9	06/18/2008	ok	06/18/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Arbor Pointe		306	08-38		08-37	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, L, ok MH 08-37	39.7 44.0 143.7 189.8 194.2 246.8 303.8 305.6	06/18/2008	ok	06/18/08	
Arbor Pointe		354	08-36		08-35	Tap, L, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 08-35	41.5 144.7 231.7 325.3 354.2	06/18/2008	ok	06/18/08	
Town	507 E Main Complaint	184	09-125		09-126	Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Offset jnt 1/2" Tap, R, ok Aband tap, R, ok Aband tap, L, ok Tap, L, ok Stopped approx 15' from MH	7.5 14.7 20.1 24.7 49.3 54.0 84.0 98.9 106.0 118.0 130.2 184.0	06/19/2008	ok	06/19/08	
Arbor Pointe		287	8-31		8-32	Tap, R, ok MH 08-32	98.4 286.6	06/19/2008	ok	06/19/08	
Arbor Pointe		136	8-31		8-25	Tap, L, ok MH 08-25	107.6 136.0	06/19/2008	ok	06/19/08	
Arbor Pointe		289	8-25		8-25A?	Tap, R, ok MH 08-25A	114.0 289.2	06/19/2008	ok	06/19/08	
Arbor Pointe		17	8-25		8-24	MH 08-24	16.8	06/19/2008	ok	06/19/08	
Arbor Pointe		88	8-25		8-26	Tap, L, ok MH 08-26	81.6 87.6	06/19/2008	ok	06/19/08	
Bellmoore		378	12-147		12-148	Tap, R, ok MH 12-148	334.5 378.1	06/20/2008	ok	06/20/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Bellmoore		393	12-147		12-145	Tap, L, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 12-145	71.0 130.7 133.8 331.4 334.5 387.2 393.1	06/20/2008	ok	06/20/08	
Bellmoore		242	12-143		12-144	Tap, L, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, L, ok MH 12-144	5.6 116.7 119.5 229.6 232.6 242.0	06/20/2008	ok	06/20/08	
Bellmoore		383	12-143		12-142	Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, L, ok Tap, R, ok MH 12-142	38.0 76.6 79.0 128.3 227.2 276.8 279.7 336.3 382.7	06/20/2008	ok	06/20/08	
Bellmoore		370	12-141		12-142	Tap, L, ok Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok MH 12-142	33.8 237.0 274.1 279.0 359.0 370.0	06/20/2008	ok	06/20/08	
Bellmoore		82	12-149		12-148	MH 12-148	81.5	06/20/2008	ok	06/20/08	
Bellmoore		130	12-149		12-150	MH 12-150	130.0	06/20/2008	ok	06/20/08	
Bellmoore		145	12-145		12-146	Tap, L, ok MH 12-146	137.8 144.9	06/20/2008	ok	06/20/08	
Bellmoore		112	12-145		12-144	Tap, L, ok MH 12-144	88.3 111.6	06/20/2008	ok	06/20/08	
Bellmoore		159	12-141		12-140	MH 12-140	158.7	06/20/2008	ok	06/20/08	
Bellmoore		395	12-140		12-139	MH 12-138	395.0	06/23/2008	ok	06/23/08	
Bellmoore		97	12-139		12-138	Tap, R, ok MH 12-138	94.1 96.7	06/23/2008	ok	06/23/08	
Bellmoore		78	12-141		12-151	Tap, L, ok MH 12-141A	72.9 78.4	06/23/2008	ok	06/23/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Mansfield	4671 Marble Ct	222	03-114		03-115	Tap, L, ok Tap, L, ok MH 03-115	69.3 128.6 221.7	06/23/2008	ok	06/23/08	
Mansfield	4671 Marble Ct	353	03-114		03-113	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-118	32.5 102.8 172.1 243.9 318.9 352.8	06/23/2008	ok	06/23/08	
Mansfield	4611 Marble Ct	321	03-113		03-112	Tap, R, ok Tap, R, ok Tap, R, ok MH 03-112	29.1 102.7 189.4 320.5	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	96	03-111		03-112	MH 03-112	96.1	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	142	03-111		03-110	Belly start 1 1/2" Tap, R, ok Tap, top, ok Belly end MH 03-110	0.0 54.1 55.7 142.0 142.0	06/23/2008	ok	06/23/08	
Mansfield	4541 Marble Ct	51	03-111		03-52	MH 03-52	51.1	06/23/2008	ok	06/23/08	
Mansfield	4522 Marble Ct	0	03-109		03-110	Too much flow		06/24/2008	Re-TV		
Mansfield	4595 Mansfield Dr	128	03-108		03-109	Tap, L, ok Tap, R, ok MH 03-109	69.6 71.2 127.9	06/24/2008	ok	06/24/08	
Mansfield	4595 Mansfield Dr	358	03-108		03-107	Belly start Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Belly stop MH 03-107	0.0 86.9 91.0 158.7 162.6 231.2 234.8 301.5 310.0 358.0 358.0	06/24/2008	ok	6/24/08	
Mansfield	4595 Mansfield Dr	296	03-108		03-104	Tap, R, ok Tap, L, ok Belly start Tap, L, ok Tap, R, ok Belly stop MH 03-104	41.7 46.3 61.0 224.5 228.6 295.8 295.8	06/24/2008	ok	06/24/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Mansfield	4725 Mansfield Dr	275	03-105		03-106	Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok MH 03-106	29.8 102.2 169.6 244.5 274.8	06/26/2008	ok	06/26/08	
Mansfield	4695 Mansfield Dr	351	03-106		03-107	Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-107	21.3 95.9 166.4 170.5 238.4 245.6 309.9 314.0 351.2	06/26/2008	ok	06/26/08	
Mansfield	4725 Miranda	223	03-101		03-102	Tap, L, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-102	2.7 6.6 42.1 44.0 113.8 115.9 182.6 186.5 223.1	06/27/2008	ok	06/27/08	
Mansfield	4715 Marble Dr	350	03-104		03-103	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 03-103	96.3 101.3 169.2 173.0 239.6 244.2 311.0 316.2 350.2	06/27/2008	ok	06/27/08	
Mansfield	4695 Miranda Dr	85	03-102		03-103	Tap, R, ok Tap, L, ok Belly start Too much water	35.1 39.0 85.0	06/27/2008	Re-TV after jet	06/27/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Mansfield	4645 Miranda Dr	175	03-103		03-102	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Too much water	26.5 30.0 97.0 102.0 169.4 175.2	06/27/2008	Re-TV after jet	06/27/08	
Waterstone Village	5716 Waterstone Village	374	30-66		30-67	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-67	24.5 122.6 159.9 229.9 290.7 347.0	07/11/2008	ok	07/11/08	
Waterstone Village	5716 Waterstone Village	160	30-66		30-91	Belly start Belly end MH 30-91	0.0 160.0 160.0	07/11/2008	ok	07/11/08	
Waterstone Village	Empty Lot	425	30-92		30-91	Tap, top, ok Tap, top, ok Tap, top, ok offset jnt, 1/2" Tap, L, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-91	2.6 34.5 73.1 93.6 101.8 150.8 166.6 221.2 232.3 285.2 296.8 361.9 377.2 425.4	07/11/2008	ok	07/11/08	
Waterstone Village	Empty Lot	0	30-67		30-68	Tap, top, ok Tap, top, ok Tap, top, ok	19.7 60.7 116.8	07/14/2008	Incomplete/too much fog to see	Re-TV done 7/21/08	Also see 7/21/08
Lakevale Estates	7422 Eastview Ct.	47	13-92		13-94	Tap, R, AD Roots	22.4 47.0	07/14/2008	Point repair/tap	07/15/08	Project 08-252
Lakevale Estates	7422 Eastview Ct.	115	13-94		13-92	Roots	114.7	07/14/2008	Point repair/tap	Same rep. as above	Project 08-252

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Waterstone Village	5844 Waterstone Village	359	30-69		30-68	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-68	46.0 97.7 165.0 220.7 280.6 345.2 358.6	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	292	30-90		30-85	MH 30-85	292.2	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	292	30-90		30-91	MH 30-91	292.0	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	347	30-89		30-90	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Mud, too deep MH 30-90	18.3 31.3 83.0 97.8 137.2 151.8 202.2 216.3 292.8 307.1 338.7 347.0	07/15/2008	ok	07/15/08	
Waterstone Village	Empty Lot	309	30-89		30-88	Tap, top, ok Tap, top, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, R, ok Tap, L, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-88	16.8 30.5 69.7 84.5 125.8 149.3 149.3 188.5 204.0 266.2 306.2 309.4	07/15/2008	ok	07/15/08	
Waterstone Village	5844 Waterstone Village	307	30-69		30-70	Tap, top, ok Tap, top, ok Offset jnt, 1/4" Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-70	3.4 42.6 43.3 67.7 130.7 194.6 258.0 305.6 307.2	07/15/2008	ok	07/15/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Waterstone Village	2906 Zachery Ct.	345	30-86		30-87	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-87	29.9 43.6 95.6 109.5 160.6 174.9 214.0 228.8 279.4 293.2 323.9 331.7 344.7	07/16/2008	ok	07/16/08	
Waterstone Village	2906 Zachery Ct.	385	30-86		30-85	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-85	4.2 18.9 57.5 71.7 123.2 136.9 188.3 202.2 254.4 268.2 332.4 347.9 384.5	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	372	30-72		30-71	Begin Small Belly 1/3 Belly ends Tap, top, ok Tap, top, ok Begin Small Belly Belly Ends Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-71	8.0 40.0 82.5 147.4 185.0 205.0 210.0 262.7 327.3 365.0 372.3	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	133	30-72		30-73	Tap, top, ok Tap, top, ok MH 30-73	75.4 90.1 132.9	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	24	30-72		30-74	MH 30-74	24.2	07/16/2008	ok	07/16/08	

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Waterstone Village	Empty Lot	217	30-74		30-75	Tap, top, ok Tap, top, ok Tap, top, ok MH 30-75	42.7 101.5 164.7 216.9	07/16/2008	ok	07/16/08	
Waterstone Village	Empty Lot	118	30-74		30-81	Tap, top, ok Tap, top, ok MH 30-81	76.4 90.9 118.3	07/17/2008	ok	07/17/08	
Waterstone Village	2905 Zachery Ct.	393	30-83		30-84	Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok Tap, R, ok Tap, top, ok MH 30-84	7.2 21.0 60.2 73.7 125.1 141.0 190.2 203.9 255.9 268.8 334.0 347.9 393.0	07/17/2008	ok	07/17/08	
Waterstone Village	Empty Lot	371	30-76		30-77	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-77	1.0 37.2 99.5 152.6 217.7 280.7 342.3 371.2	07/17/2008	ok	07/17/08	
Waterstone Village	Empty Lot	338	30-83		30-82	Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok Tap, top, ok Tap, L, ok MH 30-82	30.2 46.2 96.5 110.4 150.8 169.0 214.0 229.5 280.7 294.7 321.5 327.1 337.5	07/17/2008	ok	07/17/08	

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Waterstone Village	Empty Lot	340	30-78		30-77	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-77	62.2 118.2 182.1 251.2 301.8 340.2	07/18/2008	ok	07/18/08	
Waterstone Village	Empty Lot	181	30-78		30-79	MH 30-79	181.0	07/18/2008	ok	07/18/08	
Waterstone Village	Empty Lot	343	30-79		30-80	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-80	31.2 46.1 111.0 124.2 190.6 206.5 249.5 263.8 313.2 327.5 343.2	07/18/2008	ok	07/18/08	
Waterstone Village	Empty Lot	292	30-84		30-79	MH 30-79	291.6	07/21/2008	ok	07/21/08	
Waterstone Village	Empty Lot	292	30-84		30-85	MH 30-85	292.0	07/21/2008	ok	07/21/08	
Waterstone Village	2833 Megan Dr.	351	30-81		30-80	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-80	14.4 26.5 76.2 88.5 141.5 155.9 195.1 209.8 260.0 274.4 325.6 339.7 351.1	07/21/2008	ok	07/21/08	
Waterstone Village	5796 Waterstone Dr	349	30-68		30-67	Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok Tap, top, ok MH 30-67	48.2 94.9 160.0 224.9 289.0 330.1 348.7	07/21/2008	ok	07/21/08	Also see 7/14/08

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVEISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Riceland	5811 Riceland	16	14-262		14-261	Tap, R, ok Tap, top, ok	6.7 16.01	07/25/2008	Partial TV done to check complaint on 7/25/08 Tap OK but 2' up main repair needs done on lateral in NSD easement	07/31/08	TV only Project 08-254
Lakevale Estates	6065 Pfafflin Complaint-same address	169	13-54		13-55	Tap, top, ok Tap, top, ok MH 13-55	15.8 25.7 168.5	08/25/2008	ok	08/25/08	TV only/not jetted
Town	Frame & Hwy 662	233	06-56		09-22	1/3 pipe/water Ab tap, R Tap, R, ok Tap, L, ok Underwater	0.0 11.3 139.3 162.8 233.0	08/27/2008	Belly put on main line report as possible repair		TV only/not jetted
Springston	3611 Carmona Dr	48	12-19		C.O.	Tap, top, ok Tap, top, ok Tap, top, ok Cleanout	21.4 28.4 44.1 47.7	08/27/2008	ok	08/27/08	TV only/not jetted Re-tv done to verify repair area--no repair needed
Springston	3611 Carmona Dr	51	12-19		12-20	Tap, L, ok MH 12-20 EOR pass 12-20	16.9 43.0 51.2	08/27/2008	ok	08/27/08	TV only/not jetted Re-tv done to verify repair area--no repair needed
Kenosha Hills	4877 Kenosha Hills (Compl. 4877 Eau Clair)	0	03-07		03-06	Entire line full of grease	10.6	09/03/2008	Investigate grade issue		See 12/19/08
Town	111 Sharon Rd. Complaint 8400 Sharon Rd	0	10-106		10-161 (dupl. CEI to chg to 10-159)	Too much water & grease	0.0	09/03/2008	Jet & Re-Tv done 9/4/08		See 9/4/08 Project 08-268
Town	111 Sharon Rd. Complaint 8400 Sharon Rd	166	10-106		10-161 (dupl. CEI to chg to 10-159)	Belly start Grease on R. side (1' +) PT, top 1/2", tap ok PT, top 1/2", tap ok Belly end MH 10-161	0.0 46.0 108.0 125.0 166.0 166.0	09/04/2008	Line replacement CEI project		Project 08-268
River Bluff	10411 Lauren Ct (Complaint recd)	282	01-31		01-35	MH 01-35	282.0	09/05/2008	ok	09/05/08	TV only/not jetted
Town	617 E. Main	0	09-137		09-155	Joint sep. New repair Tap, R, ok	48.0 180.0 250.0	09/19/2008	ok	09/19/08	Also see below

(Lt Yellow) Debris & Roots	(Tan) Roots	(Grey) Silt	(Lavender) Mud	(Rose) Grease	(Aqua) sliplr	(Lime) tap and main repair					
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Town	625 E. Main	396	09-155		09-137	New repair Aban tap Tap, top, ok Tap, top, ok New Repair Tap, top, ok Tap, top, ok EOR	27.0 45.3 99.5 126.3 211.3 241.6 304.5 396.4	09/19/2008	ok Done for complaint	09/19/08	Also see above entry
Windsor Point	200 Gate Blvd	205	06-14		06-15	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok MH 06-15	21.5 73.1 149.6 200.6 205.0	09/23/2008	ok	09/23/08	TV only/Aeries demo
Windsor Point	200 Gate Blvd	403	06-14		06-13	Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok Tap, L, ok MH 06-13	7.6 35.0 73.3 99.6 138.6 177.2 216.2 241.9 281.2 307.3 383.1 395.3 402.6	09/23/2008	ok	09/23/08	TV only/Aeries demo
Windsor Point	112 Fairfax	78	06-10		06-09	Tap, R, ok Tap, L, ok Tap, R, ok Stop	12.3 25.9 78.0 78.0	09/24/2008	ok	09/24/08	TV only/Aeries demo
Windsor Point	112 Fairfax	92	06-10		06-11	Tap, L, ok Tap, R, ok Tap, L, ok Tap, R, ok stop & change head	12.6 27.0 78.2 91.6 91.6	09/24/2008	ok	09/24/08	TV only/Aeries demo
Green Springs Valley	4744 Elm Drive 8222 Sycamore/Complaint	101	11-213		11-212	New repair/drop 1/2" Tap,left, ok	97.0 101.3	11/05/2008	ok/This was a partial run to check repair was ok	11/05/08	TV only

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEVISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
South Broadview	5135 W Sherwood	215	14-12		14-13	Tap, top, lgt roots Tap, top, ok Offset jnt, 1/4" Tap, left, ok Tap, right, ok PT, top, 1 1/2" down Partial run	28.3 32.7 136.1 138.0 139.1 214.6 214.6	11/05/2008	Tap repair		Project 08-55 TV only to check repair location
Twin Oaks	7233 Oakdale Complaint for same address	3	15-116		Dead End	EOR into 6" lateral	2.7	12/01/2008	Point repair		Project 08-267 TV only/Dye test & root cut
Forest Park	702 Forest Park (compl.)	0	14-257		13-241	Belly start Belly end Tap, L, roots, bad Rap, L, roots, bad Tap, L, roots, minor Tap, right MH 13-241 RUJ, med RUJ, lgt	114.0 140.5 161.7 286.5 307.6 314.0 351.7	12/01/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Forest Park	714 Carole Place	0	14-257		13-241	Belly start Belly end Protruding tap, right Cant get by	0.0 12.0 52.0	12/04/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Forest Park	634 Forest Park Dr	0	13-241		14-257	Tap, R Tap, L Tap, L Tap, R Tap, L Tap, R Tap, L Tap, R PT, L Can't get by	.2 19.0 149.9 151.6 171.0 173.2 194.5 196.2 258.0	12/04/2008	See TV done 12/17/08 for repairs		Project 08-269 Project 08-270 Project 08-271
Hillview	7433 Lenn Ln	4	15-132		Deadend	Deadend	4.1	12/04/2008	ok	12/04/08	TV only
Newburgh Hgts Apt.	5322 Fernwood	36	14-212		New MH 14-289	New MH 14-289	36	12/09/2008	ok	12/09/08	TV only
Newburgh Hgts Apt.	5322 Fernwood	159	New MH 14-289		14-213	Tap, R, ok MH 14-213	59.2 158.5	12/09/2008	ok	12/09/08	TV only

(Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments
Alanton	8053 Cedar Point Dr. Comp. 8025 Cedar Point	192	12A-09		12A-10	Tap, R, ok Tap, L, ok Tap R, ok Tap, L, ok Small belly start Belly end Tap, R, ok Tap, L, MH 12A-10	25.9 28.5 93.0 95.8 126.8 130.2 154.5 156.8 192.2	12/09/2008	ok	12/09/08	
Green Springs Valley	8333 Poplar Dr (Compl. 8297 Oak Dr.)	0	11-210		11-211	Tap, R, ok Tap, R, roots, hvy Roots, hvy	98.9 151.9 168.0	12/09/2008	Re-TV see 12/12/08		
Green Springs Valley	8297 Oak Dr. (Compl. Same address)	0	11-211		11-210	PT, L Offset jnt, new rep., tap L	5.0 28.0	12/10/2008	Re-TV see 12/12/08		
Green Springs Valley	8400 Sycamore 8297 Oak Dr. 8388 Sycamore 8366 Sycamore Complaint 8297 Oak Dr	276	11-210		11-211	Tap, R, O/S main, OK Tap, R, ok Tap, R, root, hvy Tap, L, mud&roots, hvy AB tap, L AB tap, R OJM, 1/2" (new rep.) Tap, R, ok Tap, R, hammer, roots MH 11-211	147.2 163.8 165.7 200.1 231.7 243.1 245.0 271.9 275.6	12/12/2008	Tap repair Tap repair Point repair Tap repair		Project 08-272 Project 08-272 Project 08-273 Project 08-274
Field Stone B	4211 Stone Garden (Compl. 4255 Stone Garden)	0	11-103		11-32	Tap, L, ok Tap, T, ok Tap, L, ok Roots hvy, grease	10.2 18.0 106.8 120.0	12/12/2008	Jet & see Re-TV done 12/16/08 for repairs		Project 08-275
Field Stone B	Next to 4244 Wind Hill Ln & Empty Lot (Compl. 4255 Stonegarden Rd)	0	11-32		11-103	Tap, L, ok Tap, R, ok Belly start	73.3 117.1 180.2	12/15/2008	Jet & see Re-TV done 12/16/08 for repairs		Project 08-275

(Lt Yellow) Debris & Roots		(Tan) Roots		(Grey) Silt		(Lavender) Mud		(Rose) Grease		(Aqua) sliplr		(Lime) tap and main repair	
2008 LINES TELVEISED													
SUBDIVISION	ADDRESS	DISTANCE TELEVISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments		
Town	251A Lamey	271	05-16		05-17	Tap, top, ok Hammer tap, L Tap, R, ok Tap, L, roots RIJ, med New repair Tap, R, ok End of new repair RIJ, med RIJ, med New repair Tap, L Tap, top Tap, top, roots hvy Hammer tap, L MH 05-17	65.0 87.2 119.0 125.0 139.3 141.5 142.5 147.3 153.1 167.3 172.8 201.0 214.1 246.1 270.5	12/19/2008	Will Re-Tv in 2009 to check if any repairs are needed	12/19/08	TV only		
Kenosha Hills	10344 Shawnee Dr	0	03-04A		03-06	Too much water	0	12/26/2008	Put on Preventive Maint Add to Main Line Replacement Project		Also see 12/19/08		
Total		58028											

<div style="display: flex; justify-content: space-between; padding: 2px;"> (Lt Yellow) Debris & Roots (Tan) Roots (Grey) Silt (Lavender) Mud (Rose) Grease (Aqua) sliplr (Lime) tap and main repair </div>											
2008 LINES TELVEISED											
SUBDIVISION	ADDRESS	DISTANCE TELEVEISED	MH#	TO	MH#	Type	Footage Location	Date of TV	Recommended Resolution	Date Resolved	Comments